



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD	Ref: CS/ASM21001990/Ktf3e2
8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811	Date: 11/01/2022
ATTN: ARNOLD CHONG	Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 9438J	Veh. Inspected	SLS 4394U
Policy No.		Coverage (\$)	0.00
Claim No.	S1M032FZ	Excess (\$)	0.00
Assign From	ARNOLD CHONG	Assign Date	10/02/2021

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE (A)	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTNGF3DH308010498	Colour	METALLIC BLACK
Odometer	248354 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50Z R18	WINDFORCE	5 mm
L/H Front Tyre	235/50Z R18	WINDFORCE	5 mm
R/H Rear Tyre	235/50Z R18	WINDFORCE	7 mm
L/H Rear Tyre	235/50Z R18	WINDFORCE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/02/2021	Inspection Date	06/04/2021
Survey held at	AERO GARAGE PTE LTD BLK 160, SIN MING DRIVE, #08-07 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**