

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : CHOW YEE HOO
494C TAMPINES ST 43
#04-354
SINGAPORE 522494

ATTN: Motor Claim Department

Your Ref No: SLQ5603X
Claim Type: Third Party
Accident Date: 05/02/2021
TP Veh Reg No: GW5374J

Estimate No: MC1901749
Date: 25 Aug 2021
Policy No: P10187309R01
Veh Reg No: SLQ5603X
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

Estimate Repair Cost to Vehicle No : SLQ5603X

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts				
LABOUR				
1 TO DO CERAMIC COATING		1 PC	150.00	100.00
			NEC	150.00 ✓
Repair Amount				S\$ 150.00
GST Amount				S\$ 10.50
Total Amount payable				S\$ 160.50

The above vehicle was surveyed by KENNETH KONG -LKK on 17/02/2021

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax 6483 6170
AUTHORISED SIGNATURE