

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHOW YEE HOO
494C TAMPINES ST 43
#04-354
SINGAPORE 522494

Estimate No: MC1901749
Date: 09 Feb 2021
Policy No: P10187309R01
Veh Reg No: SLQ5603X
Make/Model: TOYOTA HARRIER
ELEGANCE 2.0

ATTN:

Your Ref No: SLQ5603X
Claim Type: Third Party
Accident Date: 05/02/2021
TP Veh Reg No: GW5374J

Estimate Repair Cost to Vehicle No :SLQ5603X

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 HEADLAMP RH	1 PC	3,478.10	X
2 HEADLAMP LOWER BRACKET RH	1 PC	98.00	X
3 FRONT BUMPER	1 PC	627.20	X
4 FRONT BUMPER SIDE RETAINER LH & RH	2 PC	230.40	X
5 FRONT BUMPER CLIPS	12 PC	50.40	X
6 FRONT FENDER COWLING RH	1 PC	522.50	X
7 FRONT FENDER COWLING CLIPS	8 PC	25.68	X
		5,032.28	
	Less 25%	1,258.07	3,774.21
LABOUR			
8 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	100
9 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	X
10 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	300.00	1000
11 TO SPRAY FRONT BUMPER.	1 PC	300.00	2200
		700.00	700.00
Total			S\$ 4,474.21
Add GST @ 7%			313.19
Total Amount Payable			S\$ 4,787.40

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED EIGHTY SEVEN AND CENTS FORTY ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE