

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Thursday, 8 April 2021 5:21 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: LPC-PAPER SURVEY FBN 7647R DONE BY GUO QIANG

Dear Shiau Chan,

Audit check done for FBN7647R, found rear OS tailboard cracked.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 8 April, 2021 4:18 PM
To: Simon Ho (LKKAUTO)
Subject: LPC-PAPER SURVEY FBN 7647R DONE BY GUO QIANG

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)