

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

15/02/2021 14:30

JOB-NO: 50113154

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHC0611B TRANS: AUTO
 MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI
 OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD
 JOB-CODE: TP SA: Ding Auto User 1

CHASSIS: KMHC851CVKU141370
 ENGINE: G4LEJU191438

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	1,700.00	0.00	1,700.00		Y	1400 ✓
2 SUNDRIES	1.00	50.00	0.00	50.00		Y	20 ✓
3 RUST PROOFING	1.00	80.00	0.00	80.00		Y	60 ✓
4 R&R FRONT RIM & TYRE LH	1.00	80.00	0.00	80.00		Y	50.7 XN1 ✓
5 R&R FRONT UNDERCARRIAGE	1.00	250.00	0.00	250.00		Y	80 XN1 ✓
6 R&R FRONT DOOR COMPONENTS LH	1.00	150.00	0.00	150.00		Y	60 ✓
7 R&R REAR PASSENGER SEAT & SEAT BELT & REAR FENDER QTR GARNISH LH & ROOF TOP LINING TO REPLACE REAR FENDER LH	1.00	280.00	0.00	280.00		Y	80 ✓
8 R&R SPARE TYRE TRAY & TRIM & SPARE TYRE & SPARE TYRE BOARD	1.00	120.00	0.00	120.00		Y	60 ✓
9 R&R REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	XN1 ✓
10 R&R FUEL LIP COVER & FUEL LIP HOUSING	1.00	120.00	0.00	120.00		Y	40 ✓
11 CONDUCT 4 WHEEL ALIGNMENT & BALANCING	1.00	250.00	0.00	250.00		Y	60 ✓
12 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200 ✓
13 RESPRAY FRONT FENDER LH	1.00	250.00	0.00	250.00		Y	200 ✓
14 RESPRAY FRONT DOOR LH	1.00	250.00	0.00	250.00		Y	200 ✓
15 RESPRAY REAR DOOR LH	1.00	250.00	0.00	250.00		Y	200 ✓
16 RESPRAY SIDE SKIRT LH	1.00	250.00	0.00	250.00		Y	100 ✓
17 RESPRAY REAR FENDER LH	1.00	250.00	0.00	250.00		Y	200 ✓
18 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200 ✓
TOTAL:		4,890.00	0.00	4,890.00			
MATERIALS							
1 FRONT BUMPER <i>scr</i>	1.00	599.68	119.94	479.74 ✓	L	Y	
2 FRONT BUMPER RETAINER LH <i>XN1</i>	1.00	48.32	9.66	38.66	L	Y	
3 FRONT FENDER LH <i>H</i>	1.00	609.54	121.91	487.63 ✓	L	Y	
4 FRONT FENDER EMBLEM-BLUE DRIVE LH <i>ne</i>	1.00	77.04	15.41	61.63 ✓	L	Y	
5 FRONT FENDER INNER SHIELD LH <i>? XN1</i>	1.00	252.85	50.57	202.28	L	Y	
6 SIDE SKIRT LH <i>tom</i>	1.00	659.60	131.92	527.68 ✓	L	Y	
7 FRONT WHEEL CAP LH <i>sm</i>	1.00	265.50	53.10	212.40 ✓	L	Y	
8 FRONT WHEEL RIM LH <i>? XN1</i>	1.00	1,224.60	244.92	979.68	L	Y	
9 FRONT TIE ROD END LH <i>? XN1</i>	1.00	156.48	31.30	125.18	L	Y	
10 FRONT STEERING RACK END LH <i>? XN1</i>	1.00	171.87	34.37	137.50	L	Y	
11 FRONT DOOR LH <i>bt</i>	1.00	1,927.30	385.46	1,541.84 ✓	L	Y	
12 FRONT DOOR LOWER MOULDING LH <i>scr</i>	1.00	286.30	57.26	229.04 ✓	L	Y	
13 REAR DOOR LOWER MOULDING LH <i>scr</i>	1.00	199.60	39.92	159.68 ✓	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
14 REAR FENDER LH <i>ht</i>	1.00	1,786.30	357.26	1,429.04			
15 REAR WHEEL CAP LH <i>sea</i>	1.00	265.50	53.10	212.40			
16 REAR BUMPER <i>Repair</i>	1.00	659.60	131.92	527.68			
17 FRONT BUMPER CLIP SET <i>m</i>	1.00	50.00	0.00	50.00	S		
18 FRONT FENDER INNER SHIELD CLIP SET LH <i>3xm</i>	1.00	35.00	0.00	35.00	S		
19 FRONT TYRE LH <i>Xm</i>	1.00	280.00	0.00	280.00	S		
20 FRONT DOOR TRIM BOARD CLIP SET LH <i>m</i>	1.00	35.00	0.00	35.00	S		
21 FRONT DOOR STICKER-COMFORT DELGRO LH <i>m</i>	1.00	120.00	0.00	120.00	S		
22 REPAIR REAR DOOR LH	1.00	0.00	0.00	0.00	S		
23 REAR DOOR STICKER-COMFORT DELGRO LOGO LH <i>m</i>	1.00	120.00	0.00	120.00	S		
24 REAR DOOR STICKER-APP STORE & BOOK NOW LH <i>m</i>	1.00	100.00	0.00	100.00	S		
25 REAR FENDER STICKER-PETROL ONLY <i>m</i>	1.00	25.00	0.00	25.00	S		
26 REAR FENDER SEALANT LH <i>m</i>	1.00	50.00	0.00	50.00	S		
27 REAR BUMPER CLIP SET <i>Xm</i>	1.00	50.00	0.00	50.00	S		
TOTAL:		10,055.08	838.02	8,217.06			
TOTAL PARTS & LABOUR:		14,945.08	1,838.02	13,107.06			

EXCESS/LOADING:\$ 0.00

No. Of Day:

9 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY:

15 / 02 / 21

SURVEYED BY:

Rasul

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*3080.00**5341.08**310.00**8731.08**9 days*