




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO21002097/QKvd3e2	
			Date: 13/04/2021	
			Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBJ 4450G	Veh. Inspected	SMQ 7349E
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2100476/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	15/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GP51340296	Colour	YELLOW
	Odometer	34688 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information				
	Accident Date	10/02/2021	Inspect Date / Time	24/02/2021 ( 02:31 PM )
	Survey held at	160 SIN MING DRIVE #05-17		
	Repairer	HIAP LEK AUTOMOBILE TRADING		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

Report Ref No. CS3/SMO21002097/QKvd3e2

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

KL

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.