

(08/11/13) wef

A.S. REC. BY: Marcus

REF:

CS/CT12100406/4+P3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

2/2/24 After CNY survey LTA \$54029
2/2/24 2/5 \$3200 conf. with Jeremy
(Red: 10,005.70 : 75%)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	700D
Vehicle Details	
Vehicle No.:	SMJ1822G
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Feb 2021
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY HYBRID 2.5G A
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	A25A0143587
Chassis No.:	AXVH701028035
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$37,260.00
Original Registration Date:	25 Feb 2019
First Registration Date:	25 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$34,164.00 17082
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Feb 2029
PARF Rebate Amount:	\$25,623.00
Intended COE Rebate Details	
COE Expiry Date:	24 Feb 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$35,403.00
COE Rebate Amount:	\$28,406.00
Total Rebate Amount:	\$54,029.00

The information contained herein is correct as at 16 Feb 2021

OK

Submit to insurance.

Not Authorized

Date : 15-Feb-21

Registration no. : SMJ1822G / Toyota Camry Hybrid 2.5G A

DOA : 11-Feb-21

Estimate No. : 19A039_SMJ1822G_CAMRY HB

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Rear door LH	dd/bent 1455-10	1798.60	✓
2	1	Rear door weatherstrip LH	nn	280.70	X
3	1	Rear door inner lock LH	nn	667.40	X
4	1	Rear door black tape LH	rec	105.40	✓
5	1	Rear fender LH	nn	1027.70	X
6	1	Rear windscreen moulding	nn	218.70	X
7	1	Rear shock absorber LH	nn	372.00	X
8	1	Rear lower arm LH	nn	486.80	X
9	1	Rear knuckle arm LH	nn	808.50	X
10	1	Rear knuckle arm bearing LH	nn	701.10	X
11	1	Rear ABS sendor LH	nn	286.50	X
12	1	Rocker panel garnish LH	dd/bent 1455-10	1079.20	✓
13	1	Rear bumper side retainer @ \$170.50	nn	341.00	X
				8173.60	
				Less 25%	
				2043.40	
				6130.20	

SPECIAL NETT ITEMS

1	1	Sundries	nn	60.00	X
2	1set	Rear door trimboard clips LH	nn	60.00	X
3	1	Rear door sealant LH	nn	80.00	X
4	1set	Front fender inner shield clips LH	nn	45.00	X
5	1set	Front fender inner trim clips RH	nn	80.00	X
6	1	Rear windscreen primer and cleaner	nn	100.00	X
7	1	Rear windscreen inner seal	nn	80.00	X
8	1	Rear windscreen sealant	nn	100.00	X
9	1	Rear tyre LH	nn	550.00	X
10	1	Rear alloy rim LH	nn	1250.00	X
11	1set	Rear bumper clips	rec	100.00	50
				2505.00	
				Parts Total	
				8635.20	

Date : 15-Feb-21

Registration no. : SMJ1822G / Toyota Camry Hybrid 2.5G A

DOA : 11-Feb-21

Estimate No. : 19A039_SMJ1822G_CAMRY HB

S/N	Qty	Item	Amount
-----	-----	------	--------

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on accident area.	1600.00	500
2	1	Check wiring system after disconnect and connect.	80.00	20
3	1	R&R LH rear door component.	480.00	50
4	1	R&R rear windscreen.	480.00	X
5	1	R&R LH rear tyre and balancing	100.00	X
6	1	R&R LH rear undercarriage.	480.00	X
7	1	To conduct wheel alignment.	150.00	60
8	1	To apply undercoating for rust roofing.	200.00	30
9	1	Spray painting on accident area.	1000.00	800
Labour Total			4570.00	

Total Parts and Labour Cost of Repair

13205.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2415-60

252

2,181.70

S-N-730

L-1460

4001.7

3201