

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1838H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER ASSY	TORN	499.90	499.90
1	FRT BUMPER FOG COVER	CRACKED	115.70	115.70
1	FRT BUMPER LH BRACKET UPPER	CRACKED	82.30	82.30
1	FRT BUMPER LH BRACKET LOWER	NOT NECESSARY	82.30	-
1	HEADLAMP PANEL LH	TO REPAIR SEE LABOUR	240.10	-
1	FRT LH FENDER	BENT	945.30	945.30
1	FRT LH FENDER SHIELD	DEFORMED	198.50	198.50
1	FRT LH FENDER EMBLEM	NECESSARY	86.50	86.50
1	FRT RH FENDER BRACKET	NOT NECESSARY	34.30	-
1	HEADLAMP ASSY LH	CRACKED	3,455.00	3,455.00
1	FRT BUMPER HOLE COVER	MISSING	28.38	28.38
1	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT LOWER ARM LH	NOT NECESSARY	637.50	-
1	KNUCKLE ARM LH	NOT NECESSARY	580.80	-
1	STG TIE ROD LH	NOT NECESSARY	159.30	-
1	WHEEL RIM	NOT NECESSARY	1,570.55	-
	LESS 25% DISCOUNT		-2,184.61	-1,358.40
			6,553.82	4,075.18
	SPECIAL NETT ITEMS			
1	TYRE (80%) (SN)	PUNCTURE	216.00	172.80
			216.00	172.80
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL LH.		900.00	525.00
	SPRAYPAINT.		700.00	500.00
	CHECK WIRING.		50.00	30.00
	TUFF KOTE.		50.00	30.00
	ADJUST FOUR WHEEL ALIGNMENT.		120.00	80.00

Report Ref No. NS/INC21002156/T1vf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

5,412.98

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX FRT SUSPENSION DAMAGED PARTS.	NOT NECESSARY	150.00	-
	REMOVE / REFIL AIRCON PARTS AND GAS.	NOT NECESSARY	120.00	-
			2,090.00	1,165.00
	GRAND TOTAL		8,859.82	5,412.98

Report Ref No. NS/INC21002156/T1vf3e2

RECOMMENDED COST OF REPAIRS (CONFIRMED)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.