



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for Sia Tze Yin (xie Zhiyun) and vehicle specifications like SLX4466U, 28/03/201, etc.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: CSM00041, Cash, 15/02/2021/ 09:37, 442 / CocoLu, 62889

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair items like RENEW FRT BUMPER, SRPAY PAINT, etc. Includes handwritten notes like '450 X 2', '350 X 3' and a large 'Estimate' watermark.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Sia Tze Yin (xie Zhiyun)	Cust No/Name	/Sia Tze Yin (Xie Zhiyun)
Blk 202 Clementi Avenue 6	Reg No/Reg Date	SLX4466U / 28/03/201
#05-4	Date In/Mileage	/ 0
Singapore 120202	Chassis No	MMCXTA03AJH020666
Contact No Mobile: 96810801	Engine No	3A92UGT8993
	Make/Model	MIT/18MY SPACE STAR 1.2 CVT (T83)
	Colour/Trim	X08 BLACK MICA / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	15/02/2021/ 09:37		442 / CocoLu	62889

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL ASSY,FR END	1.00	797.00	00.00	797.00
M PANEL,AIR GUIDE SIDE,RH	1.00	8.00	00.00	8.00
M HEADLAMP ASSY,RH / CRM	1.00	1832.00	00.00	1832.00

Steer (LKK) 15/2/21, 10.30am

00-NM AL

Estimate

Excess ?

By Bel Sy

5 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

	Nett	10,096.00
7% GST on	10096.00	706.72
	Total Payable	10,802.72

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.