


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699


TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMJ 7843 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND RENEW REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ / 280.00 /	
2	TO RENEW 1/4 GLASS TO FACILLITATE FENDER RENEWAL.	S/N \$ / 300.00 /	
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS. (side agent)	S/N \$ 400.00 Xnn	
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS.	S/N \$ / 200.00 /	
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ / 1,400.00 /	
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ / 1,400.00 /	
SUB-TOTAL LABOUR CHARGES		: \$ 3,980.00	

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMJ 7843 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. @ 500	\$ 5,600.00	3000 /
8	TO RESPRAY REAR BUMPER, LHS REAR DOOR, LHS REAR FENDER, DOOR HANDLE, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS. 3.5 + 100 + 550	\$ 4,850.00	1925 2575 /
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	/
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 14,902.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 7843 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR FENDER-LH <i>bl</i>	1	\$	4,140.00	<i>3312</i>
2	REAR SIDE WINDOW-LH <i>re</i>	1	\$	292.00	<i>233.66</i>
3	REAR SIDE WINDOW TRIM STRIPS-LH <i>re</i>	1	\$	261.00	<i>208.80</i>
4	REAR WHEEL HOUSING LINER-LH <i>X su</i>	1	\$	240.00	
5	REAR WHEEL HOUSING LINER ATTACHMENT PARTS-LH <i>X su</i>	1	\$	57.00	
6	REAR DOOR-LH <i>bl</i>	1	\$	2,767.00	<i>2213.60</i>
7	REAR DOOR OUTER SEAL-LH <i>re</i>	1	\$	161.00	<i>128.40</i>
8	BONDING AGENT <i>re X nn</i>	1	\$	49.00	
9	CLEANING SOLUTION <i>re X nn</i>	1	\$	68.00	
10	APPLICATOR <i>re X nn</i>	1	\$	8.00	
11	REAR DOOR CATCH-LH <i>re</i>	1	\$	94.00	<i>74.80</i>
12	REAR DOOR ATTACHMENT PARTS-LH <i>re ? X su</i>	1	\$	129.00	
13	REAR DOOR HANDLE EXTERIOR-LH <i>re</i>	1	\$	374.00	
14	REAR DOOR HANDLE HOUSING-LH <i>X su</i>	1	\$	52.00	
15	REAR ALUMINIUM RIM-LH <i>re</i>	1	\$	1,166.00	<i>932.80</i>
16	ACRYLIC SEALANT <i>re</i>	S/N	\$	180.00	<i>/</i>
17	CAVITY WAX <i>re</i>	S/N	\$	140.00	<i>/</i>
18	STONE CHIP <i>re</i>	S/N	\$	180.00	<i>/</i>
19	METAL FILLIER POWDER <i>re</i>	S/N	\$	280.00	<i>/</i>
20	1/4 GLASS SEALANT <i>re</i>	S/N	\$	100.00	<i>/</i>
21	SUNDRIES <i>re</i>		\$	400.00	<i>16.64</i>
TOTAL SPARE PARTS			:	\$	11,138.00
TOTAL LABOUR CHARGES			:	\$	14,902.00
GRAND TOTAL			:	\$	26,040.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasul - 4p 90010068

: 16/02/2021 @ 1420

: 12 days

: EXCESS: TAA

: Revers

: Resurvey before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT