

Lion City Rentals Pte Ltd
CARROS CENTER
 60 JALAN LAM HUAT #04-01 S(737869)
 Main +65 62524991

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ms LONPAC Insurance Bhd

Date: 16/02/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLF2998J

CHASSIS NO : NSP1707039693

MAKE / MODEL : Toyota Sienta 1.5X Auto

DATE OF ACCIDENT : 08/02/2021

YOUR INSURED VEHICLE NUMBER :YN7812H

MILEAGE : 324564 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	Front bumper cover / def.	1PC	\$ 900.00	\$ 900.00	679
2	Front bumper RH side bracket X <i>src</i>	1PC	\$ 90.00	\$ 90.00	X
3	Front bumper RH retainer X <i>src</i>	1PC	\$ 120.00	\$ 120.00	X
4	Front bumper reinforcement X <i>src</i>	1PC	\$ 380.00	\$ 380.00	X
5	Front bumper energy absorber X <i>src</i>	1PC	\$ 120.00	\$ 120.00	X
6	Front grille X <i>src</i>	1PC	\$ 596.25	\$ 596.25	X
7	Front bonnet / bp	1PC	\$ 1,288.50	\$ 1,288.50	927.80
8	Front bonnet rubber seal X <i>src</i>	1PC	\$ 45.00	\$ 45.00	X
9	Front bonnet lock / BT	1PC	\$ 192.00	\$ 192.00	140.
10	Front bonnet lock catch X <i>src</i>	1PC	\$ 80.00	\$ 80.00	X
11	F/R headlamp X <i>src</i>	1PC	\$ 990.00	\$ 990.00	X
LIST TOTAL S\$:				\$ 4,801.75	1,746.80
25.00% DISCOUNT S\$:				\$ 1,200.44	-25%
				\$ 3,601.31	1,310.10

SPECIAL NETT

1	Bumper clips / NEC	1 SET	\$ 80.00	30
2	Front number plate X <i>src</i>	1PC	\$ 50.00	X
Special Nett Total S\$:			\$ 130.00	30

LABOUR CHARGES

1	To labour charge for removing front bumper, support panel, front bonnet out to facilitate replacement of parts	\$ 1,250.00	500
2	To respray front bumper, front bonnet, both front fenders, support panel and F/L wheel housing	\$ 900.00	400

LABOUR TOTAL S\$:	\$ 2,150.00	900
TOTAL S\$:	\$ 5,881.31	
7% GST	\$ 411.69	
GRAND TOTAL S\$:	\$ 6,293.00	

Repair day - 3 days

L/S

After paint photo

Sun Pin (LKK)

17/02/2021

Tp without prejudice

L/S

\$1,800

3 days

1,310.10
30

900
2,240.10

-20%

1,792.08