

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21002226/BVF3E2

**Date:** 23/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SMW5940D

**Insured Vehicle No :** GBH7538D

Date of Loss: 06/02/2021

Nature of Claim: TP

Claim No: 8029906900SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW5940D**

Make & Model: TOYOTA SIENTA, 1.5 (A)

Engine No: 2NR1150821

Reg. Date: 27/11/2020 (Man. Year: 2019)

Chassis No: NSP1727009822

Colour: Silver

Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Rear Tyre Size: 205/50 R16

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 17/02/2021 Inspected At:

Lian Heng Painter Company  
160 SIN MING DRIVE, #06-10 SIN MING  
AUTOCITY  
Singapore 575722

Estimated Period of Repair: 0.0 days

**Adjuster:** Lim Teow Guan

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$90,000.00
OMV :	\$24,639.00
PARF Rebate (1) :	\$19,871.00
Quota Premium Paid :	\$32,699.00
COE Rebate (2) :	\$31,899.00
Total Rebate (1) + (2) = :	\$51,770.00

The total amount incurred will be Market Value \$90,000.00 minus Total Rebate \$51,770.00= \$38,230.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >