



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI21002256/Ktd3e2	
			Date: 02/08/2021	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 4759M	Veh. Inspected	JSG 5763	
Policy No.		Coverage (\$)	0.00	
Claim No.	D20004402MFSH	Excess (\$)	0.00	
Assign From	AINI BINTE	Assign Date	17/02/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YAMAHA 135	c.c	134	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	PMYUG0420H0094169	Colour	WHITE / GREY / BLACK	
Odometer	66802 KM	Steering	JAMMED	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	70/90 R17	MICHELIN	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90 R17	PIRELLI	5 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/10/2020	Inspection Date	09/03/2021	
Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	