

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676 Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500 Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Industrial Vehicles. Financial Services. 41,000 Served. And Counting.

21 October 2021

Our Reference: SLH7860D Your Reference: SHD2456P

India International Insurance Pte Ltd

64 Cecil Street

#04-02

Singapore 049711

Attn: Motor Claims Dept.

Dear Sir,

Subject: Accident Involving SLH7860D and SHD2456P along Yishun Ave 1 on 14/02/2021

We refer to the above case.

We are instructed by our client to file claim for the damages against your insured.

Our client has suffered loss and damage as a result of your Insured's negligence in the driving of vehicle No. SHD2456P.

We quantify our client's claim as follows:

	Total	S\$	2,861.00
3.	TP Insurer Search Fees	S\$	-
2.	Loss of Use (\$100 X 4 days)	S\$	400.00
1.	Cost of Repair	S\$	2,461.00

We hereby append the following relevant documents for your perusal:

- I. Repair bill tax invoice
- II. Letter of authority

Please let us know within the next 14 days from the received of this letter, whether you are prepared to accept all the above amount.



Best regards,

Yin Siew

Customer Service Advisor, Motor Claims

Goldbell Engineering Pte Ltd

Mobile: 9763 6433

Email: konyinsiew@goldbell.com.sg











LETTER OF AUTHORITY

I/We, Ngo Yun Ling Joanne, owner of SLH7860D (Vehicle no.) hereby authorize GOLDBELL ENGINEERING PTE LTD to act on my/our behalf with respect to my/our claim for repair costs and/or rental and/or loss of use for my vehicle no. SLH7860D that was damage pursuant to the accident which occurred on 14/02/2021 at/along Yishun Ave 1 involving vehicle no. SHD 2456P.

I/We permit <u>GOLDBELL ENGINEERING PTE LTD</u> to have full discretion to settle my/our above-mentioned claim in a manner that they deem fit and to sign any discharge voucher or receive any payment on my/our behalf further to the settlement of my/our claim with payment cheque/s being made in favor of GOLDBELL ENGINEERING PTE LTD.

I/We authorize GOLDBELL ENGINEERING PTE LTD to have full discretion in the usage of my/our (owner and or driver) NRIC, work permit, driving license and whatsoever identification card, indemnity against PDPA terms and conditions.

I/We acknowledge that any settlement that <u>GOLDBELL ENGINEERING PTE LTD</u> may reach on my/our behalf is in full and final settlement of my/our property damage claims against the owner/driver/ motor insurer of the third party vehicle bearing registration number <u>SHD2456P</u> and is on a without prejudice / without admission of liability basis insofar as the driver/ owner/ motor insurer of vehicle concerned.

Date this day of	(month) (year)
<u>Claimant</u> (Vehicle owner or Company representative)	<u>Vehicle Driver</u>
x de	
Signature	Signature
Mgo Yun Ling Jeanne	
Full name as per Identiy card	Full name as per Identiy card
Company Stamp if applicable	Company Stamp if applicable



INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792k | GST. Reg. No. M2-0078806-X 64 | Cecil Street | #04 | #05 | #06-02 | IOB Building | Singapore 049711 Email insure@iii.com.sg Website www.iii.com.sg Office (65) 63476100

Fax (65) 62244174

Without Prejudice to any claim for personal injury

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MFL2021D0000730 Claimant Ref SLH7860D

	Dell Engineering Pte Lta_ ("the workshop" ted Surveyor of India International Insurance Pte Ltd	, ,	9
of Surveyor) wit	h respect to the amount claimed for S\frac{1,400}{}$.	00(Global Sum)	st). Of the control o
coo/rental), CC	(search fee), vehicle no. SLH7860D that		ant to the accident which occurred
on 14/02/2021		· · ·	ving vehicle no. SHD2456P (insured
vehicle). This is p	pursuant to the inspection conducted on17/02/2021_	_ (date) at "the workshop)".
claimant") of ve	nat we/I are/am authorized by the owner Ngc chicle no.SLH7860D to make the claim as set out in his/her behalf in a manner that we/I deem fit. We/I	, , ,	and we/I have full authority to settle
they will or ha	nfirm that we/l will indemnify India International Insuve already incurred in the event that "the third pagainst the former for any loss and expenses suffered to the damage to SLH7860D (vehicle no.) as a result of the damage to SLH7860D (vehicle no.)	rty claimant" after the	e above said agreement lodges a
	hat the agreement reached above is in full and fire accident and that further this settlement is reached.		• •
This agreement dispute arising of	is subject to the application of Singapore law and tout of the same.	he Singapore Courts h	nave exclusive jurisdiction over any
We/I authorize	e you to pay the total amount of S\$ 1,400.00 to	Goldbell Engine	eering Pte Ltd
Dated this1.5	5 day of1.1		
CLAIMANT:	4 A TENER	WITNESS:	((IKK))
Signature:	Signed by "the workshop" (with chop)	Signature:	Signed by appointed Surveyor
Name:	Kon Yin Siew	Name:	LKK Auto Consultants Pte Ltd
NRIC:	G2xxxx803U	NRIC:	199607198R
Address:	Block 5035 Ang Mo Kio Industrial Park 2	Address:	51 Ubi Avenue 1
	#01-367, S569538		#01-25 Paya Ubi Ind. Park S(408933)
Nationality:		Nationality:	
Occupation:		Occupation:	



Industrial Vehicles. Financial Services. 41,000 Served. And Counting.

64 CECIL STREET

#04-02 IOB BUILDING

SINGAPORE 049711

INDIA INTERNATIONAL INSURANCE PTE LTD

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No : 198003963G

Page

1 / 1

TAX INVOICE

GST Reg No.

: M9-0002514-E

Invoice No.

EXI00296476

Invoice Date.

21-10-2021

Account No.

C00001902

Quotation No.

127901

Work Order No.

1174898

Service Centre. Agreement No. ANG MO KIO GBE~61814

PARTICULARS AMOUNT SGD Rea No SLH7860D Chassis No ZSU600015944 Engine No 3ZRB389681 Model No TOYOTA HARRIER Mileage SRR No ACCIDENT REPAIR: GBE/SVC/SALES-AMK95 **DATE OF ACCIDENT: 14/02/2021** POLICY NO.: AVPPSB0551422002 **** TP CLAIM - INDIA **** QTY Disc Net Price Ext Price Description COSTS OF REPAIR - LUMP 2300.00 Ν 2300.00 SUM Parts Charges: 2300.00

Please make all cheques payable to GOLDBELL ENGINEERING PTE LTD. When making payment, please quote our invoice numbers. No receipts will be issued for Cheque Payments.

Terms and conditions of sales

Interest at 1.5% per month will be charged on overdue account

This is a computer generated document. No signature is required.

E. & O. E







Sub Total:

TOTAL

GST @ 7.00 %





2300.00

161.00

2461.00

Claim Audit

17 Feb 1 2021 15:43 17 Feb 2 2021 15:43 17 Feb 3 2021 15:43 17 Feb 4 2021 15:43 17 Feb	Clm Dtl Modified Clm Veh Model Changed	Remarks Claimant's Name: -> NGO YUN LING JOANNE. (204715) TOYOTA HARRIER 2.0 Premium (A).	[A] Lee Si Li
1 2021 15:43 17 Feb 2 2021 15:43 17 Feb 3 2021 15:43 17 Feb 4 2021 15:43	Modified Clm Veh Model Changed Clm		
2 2021 15:43 17 Feb 3 2021 15:43 17 Feb 4 2021 15:43	Model Changed Clm	(204715) TOYOTA HARRIER 2.0 Premium (A)	
3 2021 15:43 17 Feb 4 2021 15:43		(2017 25) FOTOM CHARACTER FORMAL (17)	[A] Lee S Li
1 2021 15:43	Created	Reg No: SLH7860D. Acct Date: 2021/02/14. Claim Type: TP. Insurer: India International Insurance Pte Lt d (HQ). Workshop: Goldbell Engineering Pte Ltd (Tuas)	[A] Lee S Li
17 Feb	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lee S Li
5 2021 15:43	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/02/26	[A] Lee S Li
17 Feb 5 2021 15:43	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lee S Li
17 Feb 7 2021 15:44	Label Added	(30653):Direct Settlement.	[A] Lee S Li
17 Feb 3 2021 15:44	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lee S Li
25 Feb 2021 10:21	Adj Mandate Request	lem:cur:Req:0.00:PODS Liability: 50% (Conflicting Version). Remarks: Pls advise if there is any video/evidence from insured. We have requested evidence from 3rd party & pending response.	[A] CHEN HSIAO TONG
25 Feb 0 2021 11:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/02/26. Mandate Remarks: We have requested for evidence from our in sured	[I] Gabrio Wee
25 Feb 1 2021 11:13	Adj Mandate Set	Maintained:We have requested for evidence from our insured	[I] Gabri Wee
09 Apr 2 2021 16:10	Adj Mandate Request	Cur.Req:0.00:Hi, Kindly advise if insured had submitted any evidence. No response from 3rd party on our request on evidence til date.	[A] CHEN HSIAO TONG
09 Apr 3 2021 17:56	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2021/02/26. Mandate Remarks: Still no evidence. We have sent a chaser	[I] Gabri Wee
09 Apr 4 2021 17:56	Adj Mandate Set	Approved:0.00:Still no evidence. We have sent a chaser	[I] Gabri Wee
14 Apr 5 2021 16:07	Mandate Request	Cur.Req:0.00:Hi, No Evidence from 3rd party and they proposed 50/50 for this matter. For your approval.	[A] CHEN HSIAO TONG
14 Apr 6 2021 16:55	Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2021/02/26. Mandate Remarks: Please proceed to settle the matter on a 50/50 basis.	[I] Gabri Wee
14 Apr 7 2021 16:55	-	Approved:0.00:Please proceed to settle the matter on a 50/50 basis.	[I] Gabri Wee
25 Oct 8 2021 23:27	Adj Rpt Initiated		[A] JOANI LEE KHAN MIN
25 Oct 9 2021 23:27	Clm Dtl Modified	Insured Name: -> Insured ID: -> Claim Conclusion: -> 3.	[A] JOANI LEE KHAN MIN
25 Oct 0 2021 23:27	Clm Dtl Modified	JPJ Reg. Date: -> 2014/09/05.	[A] JOANI LEE KHAN MIN
25 Oct 1 2021 23:27	Details Notified		[A] JOANI LEE KHAN MIN
29 Oct 2 2021 08:48	Mandate Request	Cur.Req:1430.50:PODS Liability: 50% *Quantum: [(a)CORw/GST: \$2,461.00 + (b)LO4(3days x \$100.00): \$400.00]@50%=\$1,430.50 *Vehicle Model: Toyota Harrier (1986cc) *4 recommendation repair days *For your approval please.	[A] CHEN HSIAO TONG
29 Oct 3 2021 09:46	Adj Mandate Set	Approved:1430.50.	[I] Gabri Wee
Dat	e From	Date To Audit Type None	Go
CTIVITY			
record			
erimen l	Billing for t	his case - Transaction History	
Bill Ref N			Amount

					(Branch)			
2670701	18 Feb 2021 09:04:22	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SLH7860D	SHD2456P	11.00
2735807	25 Oct 2021 23:27:37	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants	LKK Auto Consultants	SLH7860D	SHD2456P	11.00