



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 1 / 2

ESTIMATE

Date : 16/02/2021 Reg No : SLH7860D
To : INDIA INTERNATIONAL INSURANCE Model : TOYOTA HARRIER
Attn. : *Not Notation* Chassis No : ZSU600015944
Office / Mobile : *61 Rm 82300d* Engine No : 3ZRB389681
Email Address : *Meiying After Repair* Quotation No. : 127901
Ref. No. :
From : GOLDBELL ENGINEERING PTE LTD D.O.A. : 14/02/2021
Attn. : KONYINSIEW Policy No. :
Office / Mobile : +65 6861 0007 Claim Type : TP CLAIMS - INDIA
Email / Fax No. : KonYinSiew@goldbell.com.sg Workshop : ANG MO KIO

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		HEADLAMP LH	<i>Sw</i> 1	2,150.00	-25	1,612.50	1,612.50 <i>X</i>
2		FRONT FENDER LH	<i>Bu</i> 1	980.00	-25	735.00	735.00 <i>✓</i>
3		FRONT BUMPER	<i>Bu</i> 1	755.00	-25	566.25	566.25 <i>✓</i>
4		FRONT BUMPER RETAINER LH	<i>Dr</i> 1	35.00	-25	26.25	26.25 <i>✓</i>
5		FRONT BUMPER TOW COVER	1	65.00	-25	48.75	<i>Sw</i> 48.75 <i>X</i>
6		FRONT BUMPER LOWER GRILLE	1	312.00	-25	234.00	<i>Sw</i> 234.00 <i>X</i>
7		FRONT FOG LAMP COVER LH	<i>Sw</i> 1	128.00	-25	96.00	96.00 <i>X</i>
8		FRONT FOG LAMP	<i>Sw</i> 1	198.00	-25	148.50	148.50 <i>X</i>
9		HEADLAMP SUPPORT PANEL LH	<i>N</i> 1	280.00	-25	210.00	210.00 <i>X</i>

PARTS TOTAL : 3,677.25

SPECIAL NETT ITEMS

FRONT BUMPER CLIPS (SET) 1 *Sw* 30.00 *✓*

PARTS TOTAL: 30.00

OUR CHARGES

TO REMOVE, REFIX & REPAIR
AFFECTED DAMAGED PARTS.
INCLUDING KNOCK OUT, WELD AND
STRAIGHTEN ON THE AFFECTED PARTS
TO REPAIR AND ALIGN LH FRONT DOOR
TO CHECK AND RECONNECT ALL
NECESSARY WIRING
TO PUTTY, CLEAN, SPRAY PAINT AND
POLISH, ETC

1800.00

Sw 300.00 *X*

200 100.00

700 1400.00

LABOUR TOTAL : 3,600.00

SUB-TOTAL : 7,307.25

GST @ 7% for \$ 7,307.25 511.51

GRAND TOTAL (\$\$) : 7,818.76

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: