



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Ref: CC4/ASM21002267/Kba3q2 Date: 23/04/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 7925K	Veh. Inspected	SJT 4181K
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03349	Excess (\$)	0.00
	Assign From		Assign Date	17/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A5 (A)	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WAUZZZF54HA032425	Colour	METALLIC RED
	Odometer	40827 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/35Z R19	MICHELIN	6 mm
	L/H Front Tyre	255/35Z R19	MICHELIN	6 mm
	R/H Rear Tyre	255/35Z R19	MICHELIN	6 mm
	L/H Rear Tyre	255/35Z R19	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/02/2021	Inspection Date	23/02/2021
	Survey held at	CHUAN HO AUTO SERVICE BLK 11 SECTOR B #01-85 SIN MING IND ESTATE SINGAPORE 575656.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	