



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref:	CS3/SMO21000351/Uvd3e2-1
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Date:	25/02/2021
		Code:	SMO
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 1401D	Veh. Inspected	SKT 6901A
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2100076/GPL	Excess (\$)	0.00
Assign From	GNOH PAU LOONG	Assign Date	17/02/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA JAZZ (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JHMGK5850FX202883	Colour	YELLOW
Odometer	105362 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/50 R16	FALKEN	6 mm
L/H Front Tyre	195/50 R16	FALKEN	6 mm
R/H Rear Tyre	195/50 R16	FALKEN	6 mm
L/H Rear Tyre	195/50 R16	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/01/2021	Inspection Date	08/01/2021
Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	