

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

\cap	ır	R	ef

456454508

Via Fax

EMALL

Date

18-2-51

Your Insured

8mg ,2092 X

Time of Fax

Date of Acc

1-7-51

Attn: Motor Claims Department

Lowphe

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

A 75730

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng

Tel: 6214 8355 or HP: 9824 0811

+ Jumani Bin Masudin

Tel: 6214 8315 or HP: 9635 5305

◆ Lim Tien Siong

Tel: 6214 8398 or HP: 9635 8546

Fax no. 6546 8156

jumanibm@cdge.com.sg

♦ Chiang Liat Choon Tel: 6214 8314 or HP: 9296 6006

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE

 Vehicle No.:
 SHA7573S
 Date
 : 18/2/2021

 Make
 : TOYOTA
 Insurance:
 LONPAC

 Model
 :
 PRIUS
 MVA
 : JUMANI

DOA : 17/2/2021 **Admin**

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
	REAR BUMPER ASSY			\$458.60
	REAR BUMPER UNDER COVER			\$552.60
	REAR BUMPER BEAM			\$318.80
	REAR BUMPER TOW COVER			\$82.30
	REAR BUMPER CLIPS			\$22.00
	TAILLAMP ASSY RH UPPER			\$557.90
	TAILLAMP ASSY RH LOWER			\$548.40
	BOOTLID COVER			\$1,126.60
	BOOTLID EMBLEM – PRIUS			\$60.80
	BOOTLID EMBLEM – HYBIRD			\$52.40
	BOOTLID EMBLEM – STAR			\$52.90
	SUB TOTAL			\$3,833.30
	LESS 25%			\$958.32
	DISCOUNTED TOTAL			\$2,874.98
	BOOTLID COMFORTDELGRO LOGO		1 1	\$30.00
	BOOTLID COMFORTDELGRO TEL.NO		1	\$30.00
	BOOTLID APPS LOGO			\$40.00
	REVERSE SESNOR			\$135.70
	REAR BUMPER MAT			\$50.00
				\$285.70
	Labour Charge			
	PANEL BEATING			\$900.00
	SPRAYPAINT			\$700.00
	CHECK WIRING			\$50.00
	TUFF KOTE			\$50.00
	REMOVE/REFIL REVERSE SENSOR			\$80.00
	REMOVE/REFIX FRT SUSPENSION DAMAGED PARTS			\$150.00
	REMOVE/REFIL AIRCON PARTS AND GAS			\$120.00
	TOTAL LABOUR			\$2,050.00
	ESTIMATE TOTAL			\$5,210.68

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



amfortDetGro Engineering Pte Ltd

Date/Time: 18.02.2021 09:12

Page: 1

ream:

ARC Repair TP(CLSO)1

JOB CARD Sales Order: JC NO.: 305454254

TARGET DATE

OMER

18

COMFORT TRANSPORTATION PTE LTD

7010045

OMER NO 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755 (R)

(O)

(P)

DUNT CARD NO.

REGN NO. SHA7573S MILEAGE MAKE: FUEL TOYOTA MODEL

PRIUS HYBRID(G4A17.02.2021 17:05

YR OF MANU. 28.02.2020

CHASSIS COPE JTDKB3FU103091132 COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 17.02.2021

NATURE: 3P 17.02.2021

S/NO

LABOR CODE

DESCRIPTION



KED	2	PASSED	OUT	BY
	~	11100000	001	- $ -$

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

SHA7573S

JU LONPAC

Vehicle No.:

Exit Pass

SHA7573S

f Service Advisor

Signature/Date

Name of Service Advisor

turned to Service Reception upon collection

To be kept by Security Guard