

ASS. REC. BY:

REF:

AIG/ 210023201kb

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/4/11 Lm & 8050d Carbur

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

P. 100

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBC 5871E
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2190136/YISHUN

Date: 18 Feb 2021

Policy No: 5115980334

Veh Reg No: GBC5871E

Make/Model: MITSUBISHI CANTER
 FB70BB1SRDEA

Chassis No: FB70BBA20549

Engine No: 4M42A91421

Reg. Date: 19/03/2013

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 16/02/2021

TP Veh Reg No: SMM3578H

Not Notified

1/1 Reg 88050h

Presumy After Rain

7 days

Estimate Repair Cost to Vehicle No :GBC5871E

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER 821.47	821.47	1 PC	821.47	✓
2 FRONT GRILLE	559.10	1 PC	559.10	✓
3 HEADLAMPS	635.10	2 PCS	1,270.20	✓
4 SIGNAL LAMPS	211.34	2 PCS	422.68	✓
5 SIDE LAMPS	184.50	2 PCS	369.00	✓
6 FRONT PANEL 1461.60	1,593.50	1 PC	1,593.50	✓
7 FRONT WIPER GARNISH	399.85	1 PC	399.85	✓
8 FRONT WINDSCREEN GLASS RUBBER	356.64	1 PC	356.64	5081m 17832m
9 AIRCON EVAPORATOR 3013.80	3,398.70	1 PC	3,398.70	✓
10 AIR-CON BLOWER	1,156.10	1 PC	1,156.10	✓
11 TAILLAMPS	200.15	2 PCS	400.30	✓
12 TAILGATE STICKER (MITSUBISHI)	104.50	1 PC	104.50	✓
			10,852.04	
		Less 25%	2,713.01	8,139.03
Special Net				
13 STICKER - 60KM/H	10.00	1 PC	10.00	✓
14 STICKER - 13 PAX	10.00	1 PC	10.00	✓
15 REAR NUMBER PLATE	18.00	1 PC	18.00	✓
			38.00	38.00
Labour				
16 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓
17 REMOVE & REFIX DASHBOARD,METER ASSY AND CHECK WIRING	250.00	1 LA	250.00	2401
18 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
19 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,SIDE LAMPS,SIGNAL LAMPS,CUT,WELD & RENEW FRT PANEL & REALIGN THE SAME	800.00	1 LA	800.00	6001

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 16/02/2021
TP Veh Reg No: SMM3578H

Estimate No: ES2190136/YISHUN
Date: 18 Feb 2021
Policy No: 5115980334
Veh Reg No: GBC5871E
Make/Model: MITSUBISHI CANTER
FB70BB1SRDEA
Chassis No: FB70BBA20549
Engine No: 4M42A91421
Reg. Date: 19/03/2013

Estimate Repair Cost to Vehicle No :GBC5871E

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
20 PUTTY & RESPRAY ON FRT PANEL,GRILLE,FRT BUMPER	680.00	1 LA	680.00	540
21 REMOVE & REFIX TAILLAMPS,REAR SPARE TYRE HOLDER,KNOCK & REPAIR REAR SPARE TYRE BRACKET & REALIGN THE SAME	500.00	1 LA	500.00	350
22 PUTTY & RESPRAY ON TAILGATE,REAR END PANEL,REAR SPARE TYRE BRACKET	500.00	1 LA	500.00	400
			2,890.00	2,890.00
Total				S\$ 11,067.03
Add GST @ 7%				774.69
Total Amount Payable				S\$ 11,841.72

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Supp 1

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 16/02/2021
TP Veh Reg No: SMM3578H

Estimate No: ES2190136/YISHUN
Date: 20 Feb 2021
Policy No: 5115980334
Veh Reg No: GBC5871E
Make/Model: MITSUBISHI CANTER
FB70BB1SRDEA
Chassis No: FB70BBA20549
Engine No: 4M42A91421
Reg. Date: 19/03/2013

Estimate Repair Cost to Vehicle No :GBC5871E

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 REAR SPARE TYRE HOLDER	310.00	1 PC	310.00	
			310.00	
	Less 25%		77.50	232.50
			Total	S\$ 232.50
			GST Amount	S\$ 16.28
			Total Amount Payable	S\$ 248.78

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	309D

Vehicle Details

Vehicle No.:	GBC5871E
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Feb 2021
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FB70BB1SRDEA
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	4M42A91421
Chassis No.:	FB70BBA20549
Maximum Power Output:	-
Open Market Value:	\$28,253.00
Original Registration Date:	19 Mar 2013
First Registration Date:	19 Mar 2013
Transfer Count:	0
Actual ARF Paid:	\$1,413.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	18 Mar 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$53,489.00
COE Rebate Amount:	\$11,157.00
Total Rebate Amount:	\$11,157.00

The information contained herein is correct as at 17 Feb 2021

OK