



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 19.02.2021
Emailed : 11.03.2021, 9.15am
Date Survey : 19.02.2021

VEHICLE NO : SMS 9269 D
MODEL : KIA CERATO 1.6 A EX
WIP : 29149

Material	:	\$	<u>5,772.80</u>
Labour	:	\$	<u>5,790.00</u>
Sub-Total	:	\$	<u>11,562.80</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>11,562.80</u>
GST 7%	:	\$	<u>809.40</u>
Grand Total	:	\$	<u>12,372.20</u>
Finalise By/Date	:	<u>LOI / 11/03/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 19/02/2021	<table> <tr> <td>Cust No/Name</td><td>/LUO JUNYANG</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMS9269D / 23/03/2020</td></tr> <tr> <td>Date In/Mileage</td><td>19/02/2021/ 16061</td></tr> <tr> <td>Chassis/Package</td><td>KNAF3416ML5069456 / #</td></tr> <tr> <td>Engine No</td><td>G4FGKH755439</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>CR5 RUNWAY RED / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/LUO JUNYANG	Reg No/Reg Date	SMS9269D / 23/03/2020	Date In/Mileage	19/02/2021/ 16061	Chassis/Package	KNAF3416ML5069456 / #	Engine No	G4FGKH755439	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK
Cust No/Name	/LUO JUNYANG														
Reg No/Reg Date	SMS9269D / 23/03/2020														
Date In/Mileage	19/02/2021/ 16061														
Chassis/Package	KNAF3416ML5069456 / #														
Engine No	G4FGKH755439														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	11/03/2021/ 09:00	BLC	260 / AiTing	29149			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, BOOT LID, REAR END PANEL, REPAIR REAR FENDER RH & LH, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 2000.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR TO FACILITATE REPAIR								✓ 80.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS TO FACILITATE REPAIR								✓ 120.00
E PNT98000 RESPRAY ON REAR BUMPER, BOOT LID, REAR END PANEL, LH & RH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1750.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUPPLY C&C LOGO								✓ 40.00
M SUNDRY APPLY SEALANT ON ACCIDENT PORTIONS								✓ 80.00
M SUNDRY SUNDRIES								✓ 20.00
E PNT88000 REPLACE LH & RH REAR COMB LAMP HOUSING, REPAIR REAR FLOOR PANEL								800.00
E PNT98000 RESPRAY ON LH & RH REAR COMB LAMP HOUSING, AND REAR FLOOR PANEL								480.00
S SPECIALISTJOB SUPPLY ONE SET OF PARKING SENSOR								220.00
S SPECIALISTJOB SUPPLY & REPLACE REAR LICENSE PLATE WITH FRAME								50.00
X COVER-RR BUMPER					1.00	✓ 651.00	20.00	520.80
X COVER-RR BUMPER LWR					1.00	✓ 241.00	20.00	192.80
X COVER-RR BUMPER FOG LAMP,RH					1.00	✓ 19.00	20.00	15.20
X LAMP ASSY-SIDE T/SIGNAL,RH					1.00	✓ 181.00	20.00	144.80

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 19/02/2021	<table> <tr> <td>Cust No/Name</td><td>/LUO JUNYANG</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMS9269D / 23/03/2020</td></tr> <tr> <td>Date In/Mileage</td><td>19/02/2021/ 16061</td></tr> <tr> <td>Chassis/Package</td><td>KNAF3416ML5069456 /#</td></tr> <tr> <td>Engine No</td><td>G4FGKH755439</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>CR5 RUNWAY RED / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/LUO JUNYANG	Reg No/Reg Date	SMS9269D / 23/03/2020	Date In/Mileage	19/02/2021/ 16061	Chassis/Package	KNAF3416ML5069456 /#	Engine No	G4FGKH755439	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK
Cust No/Name	/LUO JUNYANG														
Reg No/Reg Date	SMS9269D / 23/03/2020														
Date In/Mileage	19/02/2021/ 16061														
Chassis/Package	KNAF3416ML5069456 /#														
Engine No	G4FGKH755439														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/03/2021/ 09:00	BLC	260 / AiTing	29149

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BEAM-RR BUMPER	1.00	✓ 318.00	20.00	254.40
X BRACKET-ASSY RR BPR SIDE UPR,R	1.00	✓ 31.00	20.00	24.80
X BRACKET ASSY-RR BPR SIDE UPR,L	1.00	✓ 25.00	20.00	20.00
X PANEL ASSY-TRUNK LID	1.00	✓ 1297.00	20.00	1037.60
X PANEL ASSY-BACK	1.00	✓ 324.00	20.00	259.20
X EMBLEM-CERATO	1.00	✓ 28.00	20.00	22.40
X LOGO ASSY-KIA SUB	1.00	✓ 32.00	20.00	25.60
X TRIM ASSY-TRUNK LID	1.00	✓ 202.00	20.00	161.60
X W/STRIP-TRUNK LID OPNG	1.00	✓ 100.00	20.00	80.00
X LAMP ASSY-REAR COMB INSIDE,LH	1.00	✓ 608.00	20.00	486.40
X LAMP ASSY-CENTER GARNISH	1.00	✓ 690.00	20.00	552.00
X COVER-RR BUMPER FOG LAMP,LH	1.00	✓ 19.00	20.00	15.20
X LAMP ASSY-REAR COMB OUTSIDE,LH	1.00	✓ 675.00	20.00	540.00
X LAMP ASSY-REAR COMB OUTSIDE,RH	1.00	✓ 675.00	20.00	540.00
X LAMP ASSY-REAR COMB INSIDE,RH	1.00	✓ 608.00	20.00	486.40
X PANEL ASSY-RR COMB LAMP HSG,LH	1.00	✓ 139.00	20.00	111.20
X PANEL ASSY-RR COMB LAMP HSG,RH	1.00	✓ 135.00	20.00	108.00
X STAY-RR BUMPER LH	1.00	✓ 65.00	20.00	52.00
X STAY-RR BUMPER RH	1.00	✓ 65.00	20.00	52.00
X CLIP	10.00	2.00	20.00	16.00
X TRIM ASSY-RR TRANSVERSE	1.00	41.00	20.00	32.80
X FILM-ANTI CHIPPNG RH	1.00	27.00	20.00	21.60

Z TEXT

AIG OD CLAIM.

DOA : 19.02.21

SURVEYOR RASUL LKK 19.02.21

POLICY NO: 2070051262

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,772.80	Nett	11,562.80
Labour	5,380.00	7% GST on	809.40
Standard Menu	0.00		
Specialist Job	270.00	Total Payable	12,372.20
Diagnostics Job	0.00		
Sundry/Others	140.00		
Total(w/o GST)	11,562.80		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMS 9269 D**

	<u>Materials</u>	<u>Cost (\$)</u>
1	Panel assy-RR comb lamp hsg, LH	139.00
2	Stay-RR bumper LH	65.00
3	Stay-RR bumper RH	65.00
4	Clips (x10)	20.00
5	Trim assy-RR transverse	41.00
6	Film-anti chippg RH	27.00

Total	357.00
Less 20% discount	71.40
Total after discount	285.60


	<u>Labour</u>	<u>Cost (\$)</u>
1	Replace LH & RH rear comb lamp housing, repair rear floor panel	800.00
2	Respray on LH & RH rear comb lamp housing, and rear floor panel	480.00
3	Supply one set of parking sensor	220.00
4	Supply & replace rear license plate with frame	50.00

Total Labour	1,550.00
Taxable amount	1,835.60
7% GST	128.49

Grand total **\$ 1,964.09**

Thank You.

Yours faithfully



LOI AI TING
Senior Officer - Admin
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240



HOME

Online



CERATO/FORTE../2020/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



ICU



CLU



IBU-SMK

9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IBU-BC M	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver. M-E-K-01-00-0240

VCI Ver. 02.51

ECU Ver. M-E-K-01-00-0181

OS Ver. Android 10