

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	18 Feb 2021 16:32	<b>Clm Veh Model Changed</b>		[ ] Merimen Administrator
2	18 Feb 2021 16:32	<b>Clm Created</b>	Reg No: SMS6334T. Policy No: 2070034930. Acct Date: 2021/02/17. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R212I0001	[I] Merimen Administrator
3	22 Feb 2021 10:29	<b>Clm Registration Modified</b>	Setl.Type:3->0. Claim Type:SC->OD.	[ ] DENISE TAY KWEE CHENG
4	22 Feb 2021 10:29	<b>Adj Clm Retrieved</b>	Adj: LKK Auto Consultants Pte Ltd (HQ)	[ ] DENISE TAY KWEE CHENG
5	22 Feb 2021 10:29	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):	[A] DENISE TAY KWEE CHENG
6	22 Feb 2021 10:29	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2021/03/03	[A] DENISE TAY KWEE CHENG
7	22 Feb 2021 10:29	<b>Adj Mandate Set</b>	Approved:0.00.Reinsp:Adj decides.	[A] DENISE TAY KWEE CHENG
8	22 Feb 2021 10:29	<b>Clm Registration Modified</b>	Rep:1137->200611.	[A] DENISE TAY KWEE CHENG
9	22 Feb 2021 10:29	<b>Clm Veh Model Changed</b>	(206234) AUDI Q8 3.0 TFSI QU TIP (A).	[A] DENISE TAY KWEE CHENG
10	22 Feb 2021 10:30	<b>Assignment 1st Accessed</b>		[A] DENISE TAY KWEE CHENG
11	22 Feb 2021 10:30	<b>Adj Adjuster Assigned</b>	[None] -> ADRIAN LING	[A] DENISE TAY KWEE CHENG
12	22 Feb 2021 13:35	<b>Clm Registration Modified</b>	Acct Time:14:30:00->14:00:00. Init.Est.->5,000 - 6,000. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Azlan, Syazairdina
13	22 Feb 2021 14:19	<b>Adj Rpt Initiated</b>		[A] HUEY YON
14	22 Feb 2021 14:19	<b>Insured Phone No Updated</b>	[6591888748] -> [+656591888748]	[A] HUEY YON
15	22 Feb 2021 14:19	<b>Clm Dtl Modified</b>	Claim Conclusion: -> 3.	[A] HUEY YON
16	22 Feb 2021 14:19	<b>Clm Dtl Modified</b>	JPJ Reg. Date: -> 2020/03/06.	[A] HUEY YON
17	22 Feb 2021 14:19	<b>Clm Details Notified</b>		[A] HUEY YON
18	22 Feb 2021 14:51	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2021/03/03	[A] SHIAU CHAN
19	22 Feb 2021 14:52	<b>Adj Mandate Request</b>	Cur Req:25073.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REP AIR.	[A] SHIAU CHAN
20	23 Feb 2021 15:45	<b>Clm Registration Modified</b>	Excess: -> 1400.00.	[I] Azlan, Syazairdina
21	23 Feb 2021 15:45	<b>Label Added</b>	(20226):Coverage Confirmed.	[A] Merimen Administrator
22	23 Feb 2021 17:19	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2021/03/03. Mandate Remarks: Vehicle may commence repair (Headlamp to reconfirm on damage assessed) Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all	[I] Lim, Kok-Chong
23	23 Feb 2021 17:19	<b>Adj Mandate Set</b>	Approved:24705.00:Vehicle may commence repair (Headlamp to reconfirm on damage assessed) Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required af	[I] Lim, Kok-Chong

Date From     Date To     Audit Type  

**ACTIVITY**

No record

**Merimen Billing for this case - Transaction History**

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2671554	22 Feb 2021 14:19:11	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMS6334T		11.00