

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	NTUC INCOME IN		Ref:	CS/INC21002429/Gtf3n2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	23/06/2021
	ATTN: HELENA TA	AN		Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJK 9667R	Veh. Inspected	i	SKB 8674L
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1120278-002	Excess (\$)		0.00
	Assign From	ANNIE KOH	Assign Date		21/02/2021
2. Vehicle Particulars & Condition					
	Make & Model	AUDI TT 2.0	c.c		1984
	Engine No.	HIDDEN	Year of Reg.		2011
	Chassis No.	TRUZZZ8J4B1026053	Colour		WHITE
	Odometer	123670 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	245/45 R17	PIRELLI		6 mm
	L/H Front Tyre	245/45 R17	PIRELLI		6 mm
	R/H Rear Tyre	245/45 R17	PIRELLI		6 mm
	L/H Rear Tyre	245/45 R17	PIRELLI		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
_					
5.	Accident Date 05/02/2021 Inspect Date / Time 23/02/2021 (12:00 PM)				
	Accident Date	05/02/2021 8 KAKI BUKIT AVE 4 #02-11 PR	<u> </u>	ııme	23/02/2021 (12:00 PM)
	Survey held at	VAG SINGAPORE PTE LTD	EIVIIER		
5a.	Repairer VAG SINGAPORE PTE LTD Remarks				
Ja.	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
					ing Days