

FASTTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

Not Authorized

Not Authorized

22/2/21 4/s \$13,500
8 days.

VEHICLE No: GBC 2615Z

NETT ITEM

1PC	FRONT BUMPER	DIS	629.10	\$899.00	✓
1PC	FRONT BUMPER BEAM	11		\$322.00	X
1PC	FRONT BUMPER SIDE RETAINER N/S	Self		\$65.00	✓
1SET	FRONT BUMPER CLIPS	11		\$38.00	✓
1PC	FRONT BUMPER FOG LAMP N/S	11		\$322.40	X
1PC	FRONT BUMPER FOG LAMP GARNISH N/S	grand	120.70	\$166.80	✓
1PC	HEADLAMP N/S	cre	486.20	\$750.50	✓
1PC	FRONT SIGNAL LAMP N/S	5/20	165.20	\$288.20	✓
1PC	FRONT DOOR N/S	body 20	1315.20	\$1,655.90	✓
2PCS	FRONT DOOR HINGES @\$101.00	Self	95x2=190	\$202.00	✓
1PC	FRONT DOOR CHECKER N/S	811		\$151.00	X
1PC	FRONT DOOR INNER RUBBER N/S	11	161.20	\$188.20	✓
1PC	FRONT DOOR INNER LOCK N/S	shock	288.50	\$315.00	✓
1PC	FRONT DOOR INNER TRIM BOARD N/S	del/cre	366.20	\$650.00	✓
1SET	FRONT DOOR INNER TRIM BOARD CLIPS N/S	11		\$38.00	✓
1PC	FRONT DOOR GLASS REGULATOR & MOTOR N/S	Self/11		\$305.90	✓
1PC	FRONT DOOR OUTER PILLAR N/S	11/11		\$1,185.20	✓
1PC	FRONT DOOR GLASS OUTER MOULDING N/S	11		\$188.50	X
1PC	FRONT STEP PANEL N/S	DIS	312.30	\$350.00	✓
1PC	FRONT STEP PANEL GARNISH N/S	DIS	366.50	\$388.20	✓
1PC	FRONT CORNER PANEL N/S	DIS	492.50	\$615.00	✓
1PC	FRONT WHEEL ARCH PANEL N/S	11/11	525.30	\$545.80	✓
1PC	FRONT WHEEL ARCH PANEL GARNISH N/S	11		\$122.90	X
1PC	FRONT DOOR MIRROR N/S			\$560.20	X
1PC	FRONT DOOR OUTER HANDLE N/S	11		\$244.80	✓
1PC	FRONT DOOR OUTER REAR PILLAR N/S	11/11		\$588.20	✓
1PC	SLIDING DOOR N/S	Self/warp	1545.20	\$1,688.20	✓
1PC	SLIDING DOOR OUTER HANDLE N/S	grand	240.80	\$285.80	✓
1PC	REAR FENDER N/S	DIS/cre	2010.30	\$2,650.20	✓
1PC	REAR FENDER INNER PANEL N/S	11		\$622.20	X
1PC	TAILGATE	DIS	1742.00	\$1,889.20	✓
1PC	TAILGATE DAMPER N/S	811		\$321.90	X
2PCS	TAILGATE HINGES @\$80.00	N/S 711	78	\$160.00	1PC
1PC	TAILGATE REAR LOGO	11	45.50	\$65.20	✓
1PC	RAER WINDSCREEN	shock	950.20	\$1,455.60	✓
1PC	REAR BUMPER	11		\$741.20	X
				\$21,026.20	

16496

S.NETT

1SET	REAR FENDER 'LALAMOVE' STICKER	11	\$420.00	X
1SET	TAILGATE 'LALAMOVE' STICKER	11	\$350.00	X
1PC	TAILGATE '70Km/h STICKER	11	\$20.00	10

1PC	TAILGATE REAR WINDSCREEN SEALANT <i>nee</i>	\$50.00	<i>40</i>
1PC	REAR WINDSCREEN INNER SEAL <i>nee</i>	\$50.00	<i>40</i>
1PC	FRONT WINDSCREEN SEALANT <i>nee</i>	\$50.00	<i>40</i>
1PC	FRONT WHEEL HUP CAP N/S <i>n</i>	\$220.00	<i>X</i>

TO CHECK WIRING	\$50.00	<i>30</i>
TO CONDUCT WHEEL ALIGNMENT	\$120.00	<i>60</i>
YO TRANSFER FRONT DOOR MECHANISM	\$100.00	<i>60</i>
TO DISMANTLE & REFIX FRONT WINDSCREEN	\$150.00	<i>100</i>
TO DISMANTLE & REFIX FRONT DASHBOARD	\$280.00	<i>180</i>
TO DISMANTLE & REFIX SLIDING DOOR MECHANISM	\$100.00	<i>50</i>
TO DISMANTLE & REPLACED REAR WINDSCREEN	\$150.00	<i>100</i>
TO TRANSFER TAILGATE MECHANISM	\$100.00	<i>50</i>
TO SPRAY RUST PROOFING	\$150.00	<i>120</i>
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,200.00	<i>1600</i>
TO PUTTY & SPRAY PAINTING	\$2,000.00	<i>1400</i>
TOTAL	\$27,586.20	

16916-4
200
13810

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: