

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims
Yr Ref: SLL 1802 R

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0173/2021/JT

From
Telephone +65 -
Telefax +65 -
Email
Our Dept
Our Ref

08-SEP-2021 Date
1 Total Pages

Dear Sir,

RE: INSURANCE CLAIM FOR SLL 1802 R - Audi A5 SB 2.0 TFSI S

With reference to the above-mentioned vehicle, no. **SLL 1802 R**, claimant, **Mr Koh Boon How**, please find the related document per attached.

1. A copy of the Original Invoice no. 85016673- S\$ 17,582.92
2. A copy of the Discharge Voucher duly signed by client.

Premium Automobiles Pte Ltd,
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Based on the above document, we would appreciate you could expedite the payment soonest possible.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG Insurance - SLL 1802 R

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLL 1802 R

Norah Khai From
 6768 9911 Telephone +65 -
 6841 1183 Telefax +65 -
 Body Repair Our Dept

PA/OD/0159/2021/NH Our Ref
 31-Mar-2021 Date
 1 Total Pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A5 SB 2.0 TFSI
Vehicle Chassis No. : WAUZZZZF50JA034274
Vehicle Regn No. : **SLL 1802 R**
Vehicle Mileage : 70,609 KM
Vehicle Owner : Mr. Koh Boon How
Certificate No : 1700073271-03
Own Damage Excess : S\$ 1,926.00 (Inclusive of 7% GST)
Accident Date : 17/03/2021
Place : Bugis Junction & Bugis Village
 Traffic Light
Repair Cost : S\$ 17582.92
WIP No. : 16112
Repairer’s Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd,
 Showroom
 9 Leng Kee Road
 Singapore 159090
 Telephone (65) 6566 1111
 Telefax (65) 6471 3733

Service & Parts Centres
 55 Ubi Rd 1
 Singapore 408699
 Telephone (65) 6336 2323
 Telefax (65) 684 11183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer’s charges that are claimable under the policy will be deemed in full and final settlement of property claim only.

Insured Signature : 
Time : 6:55 pm
Date : 31/3/2021

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:02

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85016673 Date : 02/09/2021 Order : SLL1802R Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
Regn No: SLL1802R (V 35454)		Regn Date: 16/11/2017	Mileage: 74033	WIP No.: 16112	
Model: A5 SPORTBACK 2.0 TFSI S tronic		Chassis: WAUZZZF50JA034274	Engine: CVK 047056	Dept: U	
You have been assisted by :- UB-Lim Kee Siang (43)					
		Details	Qty	Unit Price	Amount
S	SUBLET	M: BNP - TO SUPPLY VEHICLE NUMBER PLATE	60.00	1.00	60.00
Q	EXC	M: 8888 Insurance Excess/Liability	-1800.00	1.00	-1,800.00
S	BODYWORK	M: TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	250.00	1.00	250.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00
S	BODYWORK	M: TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO DISMANTLE AND REINSTALL LHS WING MIRROR ASSY.	280.00	1.00	280.00
S	BODYWORK	M: TO RESPRAY LHS FRONT DOOR AND RHS A-PILLAR UPPER.	1100.00	1.00	1,100.00
X	A8W6807550J	FOAM INSER(LAST)	1.00	124.00	99.20
X	A8W6807081B	COVER(LAST) AP	1.00	127.00	101.60
X	A8K0010520A	STICKER AP	1.00	13.60	10.88
X	A8W0010515A	STICKER AP	1.00	7.10	5.68
X	A8W6807771	BRACKET(LAST) AP	1.00	137.00	109.60
X	A8W6823029	HOOD	1.00	3312.00	2,649.60

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 15:02

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85016673	Account: A0006 (T 0)
	Date : 02/09/2021	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SLL1802R	
	Term : 30	
Regn No: SLL1802R (V 35454)	Regn Date: 16/11/2017	Mileage: 74033
Model: A5 SPORTBACK 2.0 TFSI S tronic	Chassis: WAUZZZF50JA034274	Engine: CVK 047056
WIP No.: 16112		
Dept: U		
You have been assisted by :- UB-Lim Kee Siang (43)		

		Details		Qty	Unit Price	Amount
X	A8E0863727A	CLIP(LAST)	Less 020%	2.00	1.10	1.76
X	A8E0863727A	(SK) CLIP	Less 020%	1.00	1.10	0.88
X	AWHT001308	NUT	Less 020%	6.00	4.00	19.20
X	A8W6823124	PROTECTION(LAST)	Less 020%	1.00	27.30	21.84
X	A8W6823125	(A) (SK) PROTECTION 3/	Less 020%	1.00	27.50	22.00
X	A8W6823126	(A) (SK) PROTECTION 3/	Less 020%	1.00	27.30	21.84
X	A8W6823529	BOWD CABLE(LAST) AP	Less 020%	1.00	57.50	46.00
X	A8W6941774E	HEADLIGHT CLAIM	Less 020%	1.00	7902.00	6,321.60
X	A8W6121284AF	AIR DUCT AP	Less 020%	1.00	30.80	24.64
X	A8W6121673B	AIR DUCT AP	Less 020%	1.00	16.00	12.80
X	A8W6121674B	AIR DUCT(LAST) AP	Less 020%	1.00	16.00	12.80
X	A8W6807110	SPOILER(LAST)	Less 020%	1.00	535.00	428.00
X	A8W0129618F	AIR DUCT AP	Less 020%	1.00	53.00	42.40
X	A8W0129617A	AIR DUCT AP	Less 020%	1.00	21.50	17.20
X	ZG-RS5B9	RS5 COVER	Less 020%	1.00	2251.00	1,800.80
X	A8W6853603A PUZ	ATT.PARTS	Less 020%	1.00	123.00	98.40
X	AG 004000M2	HYDRAULIC OIL ALLAN	Less 020%	1.00	51.40	41.12
X	A4K0853651B RU6	GRILLE	Less 020%	1.00	2326.00	1,860.80

Parts 13,770.64
Labour 0.00
Sublet 4,462.00
Menus 0.00
Lubricant 0.00

Sub-Total 16,432.64

7% GST 1,150.28

Grand Total 17,582.92



Received by

For & on behalf of
Premium Automobiles Pte Ltd