


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 4094 J


S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ / 800.00 /	
2	TO DISMANTLE AND RENEW LHS FRONT DOOR, LHS REAR DOOR AND LHS SILL PANEL TRIM. TO REPAIR LHS REAR FENDER. RE-ORAGNIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,600.00 1500 /	
3 ²⁰⁰	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLES, LHS SILL PANEL TRIM AND LHS REAR FENDER.	\$ 4,300.00 2400 /	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ / 192.00 /	
TOTAL LABOUR CHARGES		: \$ 8,892.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4094 J


S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT DOOR-LH <i>lt</i>	\$	3,884.00	<i>3107.20</i>
2 FRONT DOOR OUTER SEAL-LH <i>rec</i>	\$	222.00	<i>177.60</i>
3 BONDING AGENT <i>rec X nn</i>	\$	49.00	
4 CLEANING SOLUTION <i>rec X nn</i>	\$	68.00	
5 APPLICATOR <i>rec X nn</i>	\$	8.00	
6 FRONT DOOR CATCH-LH <i>rec</i>	\$	120.00	<i>96.00</i>
7 FRONT DOOR TRIM-LH <i>? ok rec</i>	\$	164.00	<i>130.80</i>
8 FRONT DOOR HANDLE TRIM PLATE-LH <i>X su</i>	\$	88.00	
9 FRONT DOOR HANDLE HOUSING-LH <i>X su</i>	\$	8.00	
10 FRONT DOOR HANDLE COVER-LH <i>regu</i>	\$	6.00	
11 REAR DOOR-LH <i>lt</i>	\$	3,884.00	<i>3107.20</i>
12 REAR DOOR OUTER SEAL-LH <i>rec</i>	\$	222.00	<i>177.60</i>
13 BONDING AGENT <i>rec X nn</i>	\$	49.00	
14 CLEANING SOLUTION <i>rec X nn</i>	\$	68.00	
15 APPLICATOR <i>rec X nn</i>	\$	8.00	
16 REAR DOOR CATCH-LH <i>rec</i>	\$	120.00	<i>96.00</i>
17 REAR WINDOW SLOT SEAL WITH TRIM STRIP-LH <i>X su</i>	\$	366.00	
18 SIDE MEMBER TRIM-LH <i>rec X su</i>	\$	869.00	
19 SIDE MEMBER TRIM ATTACHMENT PARS-LH <i>rec</i>	\$	130.00	<i>104.00</i>
20 ADHESIVE TAPE FOR SIDE MEMBER TRIM <i>rec</i>	\$	212.00	<i>169.60</i>
21 SUNDRIES <i>?</i>	\$	300.00	
TOTAL SPARE PARTS	:	\$ 10,845.00	
TOTAL LABOUR CHARGES	:	\$ 8,892.00	
GRAND TOTAL	:	\$ 19,737.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasul - Hp 96010068
: 22/02/2021 @ 1030
: 8 days
: EXCESS: TBA
: PERVAH
: Repair before part

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT