

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 12 Mar 2021

Preliminary Advice

Insured Vehicle No : GBG3179M

TP Vehicle No : YP7833L

Make : MITSUBISHI CANTER

Date of Inspection : 23/02/2021

Inspection At : FASTECH AUTO PTE LTD (HQ)
1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY
SINGAPORE 417883

Accident Date : 23/02/2021

Assignment Date : 25/02/2021

Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,910.50
Revised Amount	:S\$	3,876.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,876.00
Lump Sum Repair	:S\$	3,100.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.