

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SCR138G

OUR REF.: SGC8889B

TO: AIG INSURANCE

CC: MOTOR CLAIMS DEPARTMENT

FAX:

*Not Authorized
Purvey After Party
2 day*

DATE: 26/2/2021
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: TOYOTA NOAH HYBRID 7-SEATER
CHASSIS NO.: ZWR800329878
ENGINE NO.: 2ZR0B90804
YEAR MADE: 2018
ACCIDENT DATE: 21 February 2021

ESTIMATE FOR VEHICLE NO.: SGC8889B

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	REAR BUMPER		1	\$ 600.00 X
2	REAR BUMPER RETAINER LH		1	\$ 160.00 X
3	REAR BUMPER RETAINER LH		1	\$ 160.00 X
4	REAR BUMPER CLIP		10	\$ 60.00 X
5	REAR BUMPER SENSOR		4	\$ 1,000.00 X
6	REAR BUMPER REFLECTOR RH		1	\$ 60.00 X
7	REAR BUMPER COVER LH		1	\$ 190.00 X
8	REAR BUMPER UPPER COVER		1	\$ 200.00 X
9	REAR MUDGUARD		1	\$ 1,500.00 X
TOTAL:				\$ 3,930.00
LESS 25%:				\$ (982.50)
PARTS TOTAL:				\$ 2,947.50

SPECIAL NETT

NUMBER PLATE & HOLDER
BODY SEALANT

1 50.00 X
1 50.00 X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS
TO REMOVE & REFIT ALL SENSOR
TO APPLY ANTI RUST COATING
TO SPRAY PAINT ON THE AFFECTED AREAS

1001
\$ 1,200.00
\$ 50.00 X
\$ 80.00 X
\$ 500.00 1,000.00

TOTAL: \$ 5,377.50
7% GST: \$ 376.43
GRAND TOTAL: \$ 5,753.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W