

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
LUM
SIEW YEE, JOYCE
813 TAMPINES STREET 81
#09-544
SINGAPORE 520813

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

23-02-2021
5211043795
201009404M
30001
2021007535/ 1
22-02-2021
CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SMR8643T	BQ13HZC0	29-01-2020	WVWZZZAUZKW154804	Golf Comfortline 1.4 TSI 92kW DSG	10,500

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	To Align LED Headlight	1	pcs.	100.00	#1	100.00	107.00
5G0807217FNGRU	Cover For Bumper Primed <i>de</i>	1	pcs.	1,247.94	#1	1,247.94	1,335.30
5G0807724F	Support Part (BUMPER INNER BRACKET RH) <i>3?</i>	1	pcs.	57.27	#1	57.27	61.28
5G0807050B	Guide Piece (BUMPER SIDE BRACKET RH) <i>3?</i>	1	pcs.	21.92	#1	21.92	23.45
5G0821106B	Fender <i>4</i>	1	pcs.	623.70	#1	623.70	667.36
5G0821136C	Cross Support RHS FENDER BRACKET <i>3?</i>	1	pcs.	33.22	#1	33.22	35.55
N 90817302	Rivitted Cap Nut <i>re</i>	4	pcs.	2.28	#1	9.12	9.76
5G0805970N	Wheelhouse Liner RHS FENDER LINER UPPER <i>3?</i>	1	pcs.	178.34	#1	178.34	190.82
5G0805912S	Wheelhouse Liner RHS FENDER LINER LOWER <i>3?</i>	1	pcs.	88.41	#1	88.41	94.60
5G2941774	Led Headlight <i>ca</i>	1	pcs.	2,759.41	#1	2,759.41	2,952.57
7P5941591AH	Steurg. H/LAMP CONTROL UNIT <i>3?</i>	1	pcs.	400.71	#1	400.71	428.76
5G0919493L	Sensor Bracket <i>re</i>	1	pcs.	12.86	#1	12.86	13.76
5G0919493J	Sensor Bracket <i>re</i>	2	pcs.	12.39	#1	24.78	26.51
5G0919494G	Sensor Bracket <i>re</i>	1	pcs.	12.86	#1	12.86	13.76
D 822150A1	Bonding Agent For Plastic <i>re</i>	1	pcs.	62.81	#1	62.81	67.21
D 180KU2A1	2k-Plastic Adhesive <i>re</i>	1	pcs.	78.91	#1	78.91	84.43
	LABOUR	3	pcs.	840.00	#1	2,520.00	2,696.40
	Spray Painting	4	pcs.	800.00	#1	3,200.00	3,424.00

Quotation valid till 01-03-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	860.00	11,332.26	7%	853.46	12,192.26	13,045.72
Total	860.00	11,332.26		853.46	12,192.26	13,045.72

Customer

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Service Advisor

Rasm
Hp 90010068
5 days
25/02/2021 @ 1030
Resurvey before paint

VOLKSWAGEN CENTRE SINGAPORE

17 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Commercial
Vehicles

Quotation

Non binding - Preview

Page

2/2

Company

AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:

Ms.
LUM
SIEW YEE, JOYCE
813 TAMPINES STREET 81
#09-544
SINGAPORE 520813

Document no.

Document date 23-02-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021007535/ 1
Job order date 22-02-2021
Service Advisor CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SMR8643T	BQ13HZC0	29-01-2020	WWZZZAUZKW154804	Golf Comfortline 1.4 I TSI 92kW DSG	10,500

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—