



All ▾ ← SBS3112



Print Cancel

**FW: accident involving SBS Transit bus SBS3112S and vehicle no: SCP9083G had taken place at/along Junction of Irwell Bank Rd & River Valley Rd, after b/s13159 20.1km toward HFI on 24/01/2021 at 0648hrs.**

Chin, Lee-Ying <Lee-Ying.Chin@aig.com>

Tue 23/2/2021 11:42 AM

To: assignments <assignments@lkkauto.com>;

Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>

Hi LKK,

Kindly assist to survey.

OI hasn't lodge GIA report.

Thanks.

Best Regards,

**Lee Ying, Chin**

Senior Claims Associate – Auto

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way, Level 10

Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@AIG.com](mailto:Lee-Ying.Chin@AIG.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Yao Tianhao

<yaoth@sbstransit.com.sg>

**Sent:** Tuesday, February 23, 2021 11:21 AM

**To:** AIG SGP, Claims-Survey

<AIGSGP\_ClaimsSurvey@aig.com>

**Cc:** Seah Hai Hua

<seahhh@sbstransit.com.sg>; Rajeshpal Singh  
S\_O Mohan Singh

<rajeshpal@sbstransit.com.sg>; Gary Chong

Kim Seng <garychong@sbstransit.com.sg>;

Linda Yeung Fook Mooi