

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5151Z*Not Authorised
Running By paint***AAD2102-016**

Vehicle No.:

24 FEB 2021

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD5151Z

JTDKB3FU003077304

TOYOTA

PRIUS

01/02/2021

III

12/12/2018

PART

- 1 COVER, FRONT BUMPER
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 FRONT BUMPER SIDE RETAINER RH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 EXTENSION, FRONT BUMPER, RH
- 1 UNIT ASSY, HEADLAMP, RH
- 1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1
- 1 LINER, FRONT FENDER, RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 EMBLEM, SIDE PANEL, RH
- 1 JAR ASSY, WINDSHIELD WASHER

LIST

\$	Bu	516.00	✓
\$	R	716.60	X
\$	Sh	79.60	✓
\$	air	80.10	✓
\$	Sh	59.30	X
\$	Sh	80.10	X
\$	Sh	120.10	X
\$	Sh	2,637.60	X
\$	Sh	960.50	X
\$	Sh	206.70	X
\$	R	977.80	✓
\$	Sh	54.60	✓
\$	Sh	219.10	✓

TOTAL**Over All Total****(PART-BY-PART) Repa****TOTAL \$ 6,708.10****25% \$ 2,828.00****\$ 8,484.00****Special Nett**

- 1 WHEEL RIM
- 1 TYRE 195/65/15
- 1 RIM COVER
- 1SET FRONT FENDER CLIP
- 1SET FRONT FENDER LINER CLIP
- 1SET FRONT BUMPER CLIP

\$	Sh	1,879.40	X
\$	Sh	350.00	X
\$	Sh	400.00	X
\$	Sh	65.00	X
\$	Sh	75.00	X
\$	Sh	90.00	✓

TOTAL \$ 2,859.40**TOTAL PARTS \$ 9,530.50**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5151Z

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion,			300l
Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	30l
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	440l
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20l
TOTAL		\$ 4,380.00	
Over All Total		\$ 15,723.40	

(PART-BY-PART) Repair Days10 days
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: