

李 汽 车 贸 易

ERZAT LEE MOTOR TRADING PTE LTD

Synergy@KB 25 Kaki Bukit Road 4

#03-37 Singapore 417800

Reg 201918537M

VEHICLE NO: FBR4608C

REG YEAR

Jul-20

VEHICLE MODEL: YAMAHA T150

VEHICLE CHASIS: MH3UG131000001373

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	Surveyor Recommendation
1	Front mudguard	1	\$ 185.00	\$ 185.00	
2	Front disk	1	\$ 225.00	\$ 225.00	
3	Front wheel axle	1	\$ 110.00	\$ 110.00	
4	Right fork assembly	1	\$ 550.00	\$ 550.00	
5	Left fork assembly	1	\$ 550.00	\$ 550.00	
6	Front fairing cover outer	1	\$ 165.00	\$ 165.00	
7	Front fairing cover emblem	1	\$ 55.00	\$ 55.00	
8	Front fairing cover inner	1	\$ 135.00	\$ 135.00	
9	Front Left fairing assembly	1	\$ 280.00	\$ 280.00	
10	Front Right fairing assembly	1	\$ 280.00	\$ 280.00	
11	Headlamp assy	1	\$ 335.00	\$ 335.00	
12	Front headlight cover	1	\$ 188.00	\$ 188.00	
13	Meter outer cover	1	\$ 155.00	\$ 155.00	
14	Meter inner cover	1	\$ 185.00	\$ 185.00	
15	Meter assy	1	\$ 650.00	\$ 650.00	
16	Centre inner fairing	1	\$ 235.00	\$ 235.00	
17	Yamaha emblem	1	\$ 40.00	\$ 40.00	
18	Radiator assy	1	\$ 550.00	\$ 550.00	
19	Brake pump assy	1	\$ 215.00	\$ 215.00	

20	Steering stem bearing	2	\$ 105.00	\$ 210.00	
21	Steering stem bracket assembly	1	\$ 265.00	\$ 265.00	
22	Handle bar	1	\$ 235.00	\$ 235.00	
23	Balancer set	1	\$ 88.00	\$ 88.00	
24	Brake lever	1	\$ 115.00	\$ 115.00	
25	Rear view mirror set	1	\$ 165.00	\$ 165.00	
26	Front footrest holder assembly	1	\$ 255.00	\$ 255.00	
27	Brake pedal assy	1	\$ 135.00	\$ 135.00	
28	Gear shifter pedal assy	1	\$ 135.00	\$ 135.00	
29	Rear Left fairing assembly	1	\$ 280.00	\$ 280.00	
30	Rear Right fairing assembly	1	\$ 280.00	\$ 280.00	
31	Left rear footrest	1	\$ 155.00	\$ 155.00	
32	Right rear footrest	1	\$ 155.00	\$ 155.00	
33	Rear signal light set	1	\$ 165.00	\$ 165.00	
34	Swing arm assy	1	\$ 600.00	\$ 600.00	

TOTAL PRICE \$ 8,326.00
LESS 10% \$ 832.60
SUB TOTAL PRICE \$ 7,493.40

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	Surveyor Recommendation
1	ERP IU	1	\$ 200.00	\$ 200.00	
2	Front number plate	1	\$ 25.00	\$ 25.00	
3	Front/Rear sport rim	2	\$ 220.00	\$ 440.00	
4	Front/Rear tyre	2	\$ 280.00	\$ 560.00	
4	Coolant	1	\$ 80.00	\$ 80.00	
5	Fork oil	1	\$ 60.00	\$ 60.00	
6	Brake fluid	1	\$ 85.00	\$ 85.00	
7	Left fairing assembly labels sticker	1	\$ 155.00	\$ 155.00	
8	Right fairing assembly labels sticker	1	\$ 155.00	\$ 155.00	

TOTAL # \$ 1,760.00 CLAIM

DETAILS: LABOUR AND SPRAY PAINTING

1	Towing charges	\$ 60.00	
2	Dismantle, replace, realign and adjust above damaged parts	\$ 600.00	

3	To knock, straighten chassis & body balancing.	\$ 320.00	
4	To remove/ refit, replace check and straighten front fork tubes.	\$ 250.00	
5	To remove/ refit and balance front sport rim	\$ 80.00	
6	Spray painting	\$ 350.00	

TOTAL \$ 1,660.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	9253.40
TOTAL LABOUR COST	:	\$	1,660.00
TOTAL REPAIR COST	:	\$	10,913.40