



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21002615/Uga3q2 Date: 05/08/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 4749G	Veh. Inspected	SGS 1582Y	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M0325I	Excess (\$)	0.00	
Assign From		Assign Date	25/02/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CIVIC 2.0 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JHMF26407S200510	Colour	WHITE	
Odometer	284091 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm	
L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	03/02/2021	Inspection Date	02/03/2021	
Survey held at				
Repairer	1ST AUTO PRO PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	