

FAQ English (SG) ▼ Elaine Kuan ▼



Service Requests



Claim [S0M02F21](#)

Reference CS/ASM21002623/R1qf3e2


Loss Date 31 January 2020

Vendor Name LKK AUTO CONSULTANTS
PTE LTD (TP)

Type of Loss Third Party Vehicle Damage

Report Date 3 Feb 2020 11:46:18 AM

Request Date 21 June 2021

Due Date

Services Re-inspection

Actions

Next Step Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident SBS3061E
Vehicle
Registration #

Make TPVD Volvo

Model B9TL

Service Address

51 Ubi Avenue 1, #01-25, , , 408933

Primary Contact/Insured

NG KOK KEONG
BLK 326 YISHUN RING ROAD, #13-1354, 760326,
Singapore
98515119

FAQ English (SG) ▼ Elaine Kuan ▼



Service Requests



Claim Handler

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

SBS
LTD

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
ASM_LKKInvoice_AC2104809.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	12 July 2021
Resurvey Photo_1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	12 July 2021

			SUBTYPE		AUTHOR	DATE UPLOADED
FAQ	English (SG) ▼	Elaine Kuan ▼				
	Service Requests	...	Invoice	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	12 July 2021