



## TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

Our Ref : GBH7542R

Yours Ref : SLL2123K

### AIG ASIA PACIFIC INSURANCE PTE. LTD.

14 June 2021

78 SHENTON WAY #07-16  
AIG BUILDING  
SINGAPORE 079120

Attn: MOTOR CLAIM DEPT

Dear Sir / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: GBH7542R & SLL2123K ON 22/02/2021 @ 09:00 HRS ALONG  
DEFU AVENUE 2

The vehicle had been surveyed by your appointed surveyor and repaired to our client's satisfaction.

We hereby submit the details of claim as follow:

Cost of Repair	:	S\$21,322.68
Loss of Use (\$ 100.00 x 12 days)	:	S\$1,200.00
Additional Loss of Use (\$ 100.00 x 2 days) -- Weekend	:	S\$200.00
GIA / LTA Search	:	S\$7.45
Towing Fees	:	S\$50.00
Parts Delay (19days x \$100/-) -- 02/03/21 to 24/03/21	:	S\$1,900.00
		<u>S\$24,680.13</u>

Kindly revert within SEVEN days. Filling which we reverse our rights to refer the matter to our solicitors.

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD

## AUTHORISATION LETTER

I, DAIMLER FLEET MANAGEMENT S'PORE PTE LTD of 1 GATEWAY DRIVE #15-08 WESTGATE TOWER SINGAPORE 608531, owner of GBH7542R hereby authorize TONG LUCK AUTO PTE LTD to act for me with my respect to our claim for repair costs and/or rental and/or loss of use for our vehicle no.: GBH7542R that was damaged pursuant to the accident which occurred on 22/02/2021 ALONG DEFU AVENUE 2 involving vehicle nos: SLL2123K

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the

Dated this 25th day of February 2021



*hshhins*

Signed by third party claimant



TONG LUCK AUTO PTE LTD

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

“We/I, **TONG LUCK AUTO PTE LTD** (“the workshop”) hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$21,322.67** (Repair Cost), **S\$1,980.00** (Loss of Use/Rental), **S\$57.45** (Disbursement) for vehicle no. **GBH 7542R** that was damaged pursuant to the accident which occurred on **22.02.2021** (date) along **DEFU LANE 2** (location) involving vehicle no/s **SLL 2123K**.

This is pursuant to the inspection conducted on **26/02/2021** (date) at “the workshop”.

We/I confirm that we/I are/am authorized by the owner **DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD** (“the third party claimant”) of vehicle no. **GBH 7542R** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by “the third party claimant”.

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that “the third party claimant” after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **GBH 7542R** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of “the third party claimant” pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 22 (day) of July (month) 2021 (year)



Signed by appointed surveyor



Signed by “the workshop” (with chop)



## TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

### TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

ATTN: AIG ASIA PACIFIC INSURANCE PTE. LTD.

TEL : 6849 8118

FAX :

YOUR REF NO : SLL2123K

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 22/02/2021

TP VEHICLE NO : SLL2123K

NO : AR202106-0035

CLAIM NO : QUOT202102-000064(01)

DATE : 14/06/2021

POLICY NO : 999995580

VEH REG : GBH7542R

MAKE/MODEL : MERCEDES BENZ VITO 109  
CDI MT LONG

CHASIS NO : WDF44760323474388

ENGINE NO : R9MA503C052160

REG. DATE : 2018

### Final Repair Cost to Vehicle No : GBH7542R

Description	Quantity	List Price	Amount
		<del>S\$</del>	<del>S\$</del>
NET PRICE			
1 Dashboard assy	1	1,591.87	1,591.87
2 Steering air bag	1	2,455.00	2,455.00
3 Passenger air bag	1	2,455.00	2,455.00
4 Air bag control unit	1	1,495.00	1,495.00
5 Front safety belt - RH / LH	2	790.00	1,580.00
6 Front safety belt - centre	1	790.00	790.00
7 Battery cut off switch	1	520.00	520.00
8 Bonnet	1	1,378.20	1,378.20
9 Bonnet lock - lower	1	122.77	122.77
10 Bonnet hinge - RH / LH	2	74.11	148.22
11 Support panel	1	590.00	590.00
12 Support panel top garnish	1	115.00	115.00
13 Support panel bracket - LH	1	48.00	48.00
14 Front fender - LH	1	788.00	788.00
15 Front fender inner shield - LH	1	188.00	188.00
16 Front fender inner shield flap - LH	1	58.00	58.00
17 Headlamp assy - LH	1	845.00	845.00
18 Front bumper	1	775.33	775.33
19 Front bumper reinforcement	1	635.88	635.88
20 Front bumper carrier - LH	1	104.00	104.00
21 Front bumper side retainer - LH	1	98.00	98.00
22 Front bumper cross member bracket - LH	1	74.00	74.00
23 Washer tank	1	145.00	145.00
24 Washer tank neck	1	58.00	58.00
25 Washer tank cover	1	28.00	28.00
26 Radiator auto fan assy	1	901.22	901.22
27 Radiator guide - LH	1	78.00	78.00
28 Radiator lower cover	1	125.00	125.00



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

## TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

ATTN: AIG ASIA PACIFIC INSURANCE PTE. LTD.

TEL : 6849 8118

FAX :

YOUR REF NO : SLL2123K

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 22/02/2021

TP VEHICLE NO : SLL2123K

NO : AR202106-0035

CLAIM NO : QUOT202102-000064(01)

DATE : 14/06/2021

POLICY NO : 999995580

VEH REG : GBH7542R

MAKE/MODEL : MERCEDES BENZ VITO 109  
CDI MT LONG

CHASIS NO : WDF44760323474388

ENGINE NO : R9MA503C052160

REG. DATE : 2018

## Final Repair Cost to Vehicle No : GBH7542R

Description	Quantity	List Price	Amount
		<del>S\$</del>	<del>S\$</del>
29 Radiator support - LH	1	48.00	48.00
30 Radiator top clips - LH	1	28.00	28.00
31 Front wheel hup cap - LH	1	88.00	88.00
32 Washer tank motor	1	188.00	188.00
33 Washer tank lower mounting	1	52.00	52.00
34 Water hose (long)	1	118.00	118.00
35 Water hose (short)	1	85.00	85.00
			18,797.49
		Less 10%	1,879.75
			16,917.74
<b>SPECIAL NET</b>			
36 Front windscreen sealant	1	40.00	40.00
37 Front fender inner shield clips - LH (set)	1	50.00	50.00
38 Front bumper clips (set)	1	50.00	50.00
39 Radiator coolant	1	50.00	50.00
40 Front number plate	1	40.00	40.00
			230.00
<b>LABOUR</b>			
41 To remove and refit front windscreen glass	1	120.00	120.00
42 To remove and refit front dashboard assy, meter and grove compartment	1	250.00	250.00
43 To remove and refit air-con condenser, radiator, inter-cooler assy and refill air-con gas	1	100.00	100.00
44 To check and rectify wiring systems	1	20.00	20.00
45 To remove and refit steering air bag, passenger air bag, airbag control unit, front both side and centre safety belt	1	300.00	300.00
46 To remove and refit battery cut off switch	1	80.00	80.00
47 To panel beat and straighten LH front chassis frame, LH front fender inner panel, including replacement of parts and align where necessary, to refit and adjust the same	1	700.00	700.00
48 To putty and spray paint on affected areas	1	600.00	600.00



## TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

### TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

ATTN: AIG ASIA PACIFIC INSURANCE PTE. LTD.

TEL : 6849 8118

FAX :

YOUR REF NO : SLL2123K

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 22/02/2021

TP VEHICLE NO : SLL2123K

NO : AR202106-0035

CLAIM NO : QUOT202102-000064(01)

DATE : 14/06/2021

POLICY NO : 999995580

VEH REG : GBH7542R

MAKE/MODEL : MERCEDES BENZ VITO 109  
CDI MT LONG

CHASIS NO : WDF44760323474388

ENGINE NO : R9MA503C052160

REG. DATE : 2018

### Final Repair Cost to Vehicle No : GBH7542R

Description	Quantity	List Price	Amount
		<del>S\$</del>	<del>S\$</del>
49 To re-programme and coding all faulty code (online)	1	450.00	450.00
50 To check wheel alignment	1	60.00	60.00
51 To open and seal up rear cushion to enable to change safetybelt	1	100.00	100.00
			2,780.00

TOTAL: **S\$19,927.74**

ADD GST @ 7%: 1,394.94

GRAND TOTAL: **S\$21,322.68**

SINGAPORE DOLLARS TWENTY-ONE THOUSAND THREE HUNDRED AND TWENTY-TWO AND CENTS SIXTY-EIGHT ONLY

E. & O.E.

TONG LUCK AUTO PTE LTD



AUTHORISED SIGNATURE

> Back to OneMotoring



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 24 Feb 2021 / 15:39:51

Receipt Date/Time : 24 Feb 2021 / 15:39:51

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-210224-002818

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SLL2123K

As at 22 Feb 2021/09:00:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SLL2123K  
Enquiry Fee  
20210224153759367460

7.00 0.49 7.49

**Sub-Total** 7.00 0.49 7.49

**Total Before Rounding** 7.00 0.49 7.49

**Rounding Difference** 0.04

**Total Amount Payable** 7.45

Paid By

518834XXXXXX2002 eNETS Credit Card 7.45

**Total** 7.45

Cash Change 0.00

Tendered Amount 7.45

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## Enquire Vehicle's Insurance Particulars

### Thank You!

The insurance details of the vehicle you enquired can be found below. If you have entered a valid email address, a copy would have been sent to you.

Vehicle No.	Incident Date/Time	Insurance Company Name
SLL2123K	22 Feb 2021 / 09:00:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Save as PDF](#)

[OK →](#)

[Print](#)



# Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

bizSAFE<sub>3</sub>

NO. 66284

## CASH SALE / JOB ORDER

Date 22/2/21

Messrs: Tong Luck  
车牌 GBH 7542R 车型 M/BENZ  
Vehicle No. GBH 7542R Model No: M/BENZ  
时间 (日/夜) 1 联络号码 81268670  
Time (day/night): 1 Contact No: 81268670  
由 Defu Lane  
Location: Defu Lane  
到 0701 Authority  
To: 0701 Authority  
银额 507 其他 Others:  
Cash \$ 507  
经手人 Authorised By:  
Tow Truck Driver Name: [Signature]

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

T. & O. E.

## Cecilia Chong (LKK Auto)

---

**From:** Cecilia Chong (LKK Auto)  
**Sent:** Wednesday, 23 June 2021 4:32 PM  
**To:** yhsyieu@hotmail.com  
**Subject:** <STANDARD NOTIFICATION LETTER> OUR REF: CC4/AIG21002629/Kga3 \*\*\* ACCIDENT INVOLVING SLL 2123K & GBH 7542R ON 22/02/2021 \*\*\*

Our Ref: CC4/AIG21002629/Kga3  
23 JUNE 2021

**YIEU HANN SHEN**

Dear Sir/Madam,

### **ACCIDENT INVOLVING SLL 2123K & GBH 7542R ON 22/02/2021**

We refer to the above accident. We are the Appointed Surveyor and Loss Adjuster Company by your Motor Insurer (AIG Asia Pacific Insurance Pte Ltd.) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

This is to inform you that we received a Third Party Claim from **GBH 7542R**.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please provide the following:

1. Accident video footage
2. Traffic Police investigation result

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

“Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.”

**Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.**

Best Regards,

Cecilia Chong | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [CeciliaChong@lkkauto.com](mailto:CeciliaChong@lkkauto.com) fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

# Print Received Message

This mail is associated with :

**\*GBH7542R (8518830517SG)**  
**[SLL2123K]**

TP

DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD

Feb 22 2021 9:00AM

[Yieu Hann Shen (Qiu Hanshen)]

Tong Luck Auto Pte Ltd

**From** **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS)**, sent on **19/07/2021 17:25 PM.**  
**To** LKK\_HQ  
**Subject** **Alert - Adj Mandate Approved (S\$24680.12) - GBH7542R - Claim Handler: Yong, Joanne**


Approved:24680.12:Pls start frm \$23,360.12 (breakdown LOU-\$60 X 33days- \$1,980.00).



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## TAX INVOICE

Invoice Name & Address				Owner Name & Vehicle Info		
TONG LUCK AUTO PTE LTD				Cust No/Name	/Daimler Fleet Management Singap	
160 SIN MING DRIVE				Reg No/Reg Date	GBH7542R*M / 14/09/2018	
#07-01/06 SIN MING AUTOCITY				Date In/Mileage	/ 61224	
SINGAPORE-575722				Chassis No	WDF44760323474388	
Attn: Terence Tan 96235378				Engine No	622951F0095011	
Contact No				Make/Model	MBCV/Vito 109KA/ L 4X	
				Colour/Trim	914 Arctic White / NA NOT APPLICABLE	
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CSC00003	Cash	02/03/2021/ 16:57	JAI	620 / Jaiganesh S	45116	25336288

Description of Goods / Services	Qty	Unit Price S\$	Amount S\$
---------------------------------	-----	----------------	------------

D DEPOSIT COLLECTED  
DEPOSIT FOR PARTS ORDERED  
(\*Deposit for parts ordered are non-refundable)

5199.81



CYCLE &amp; CARRIAGE

188 PANDAN LOOP


MERCEDES BENZ SERVICE CENTRE(CV)  
SINGAPORE 128378

SALE

DATE/TIME: 02MAR21 17:00  
TID:40205214 MID:168168350203  
INVOICE#: 000046 BATCH#: 000051  
MASTERCARD EXPIRY  
XXXX XXXX XXXX 2002 XX/XX  
APPR CODE:166998 HOST: MOTO  
MANUAL ENTRY RRN:106109000046  
INV NO 25336288

TOTAL SGD 5563.80

SIGN X  
I AGREE TO PAY THE ABOVE TOTAL AMOUNT  
ACCORDING TO CARD ISSUER AGREEMENT  
\*\*\* CUSTOMER COPY \*\*\*



Guarantee Your Warranty, Maintain with Cycle &amp; Carriage!

Parts	0.00	Nett	5,199.81
Labour	0.00	7% GST on	363.99
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	5,563.80
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	5,199.81	Total Due	5,563.80
Total(w/o GST)	5,199.81		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany


Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6771 4389  
Fax: 6775 6310  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
TONG LUCK AUTO PTE LTD	Cust No/Name /Daimler Fleet Management Singap
160 SIN MING DRIVE	Reg No/Reg Date GBH7542R*M / 14/09/2018
#07-01/06 SIN MING AUTOCITY	Date In/Mileage / 61224
SINGAPORE-575722	Chassis No WDF44760323474388
Attn: Terence Tan 96235378	Engine No 622951F0095011
Contact No	Make/Model MBCV/Vito 109KA/ L 4X
	Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CSC00003	Cash	24/03/2021/ 14:49	JAI	620 / Jaiganesh S	45116	25336936
Description of Goods / Services				Qty	Unit Price S\$	Amount S\$

Z Customer request						
Air Bg & Seat Belt Replace						
D LESS DEPOSIT						-5199.81
REF TO INVOICE NO:25336288						
INVOICE DATE:02.03.2021						
X DRIVER AIRBAG	1.00	2186.05	20.00			1748.84
X FRONT PASSENGER AIRBAG	1.00	2186.05	20.00			1748.84
X SEAT BELT	1.00	736.78	20.00			589.42
X SEAT BELT	1.00	654.04	20.00			523.23
X SEAT BELT	1.00	736.85	20.00			589.48

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,199.81	Nett	0.00
Labour	0.00		
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	0.00
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	-5,199.81	Total Due	0.00
Total(w/o GST)	0.00		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6771 4389  
Fax: 6775 6310  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

WIP No: 45116

GBH7542R\*M

## PART REQUISITION

Owner Name & Vehicle Info			
Customer Name	TONG LUCK AUTO PTE LTD	Date/Time Printed	24/03/2021 14:40
Reg No/Reg Date	GBH7542R*M / 14/09/2018	Requisition No	25252827
Chassis No	WDF44760323474388	WIP No	45116
Make/Model	MBCV / 44760323-S	Account No/Terms	CSC00003/ CASH
Blk No/Last Mileage	61224	Operator	W 604 Vincent Kum

Part Number	Part Description	Quantity	Location	Code
MA447 860 07 00/ 9C94 ✓	SEAT BELT	1.00		A/I/W
MA000 860 14 02/ 9116 ✓	DRIVER AIRBAG	1.00	24040520	A/I/W
MA447 860 02 02/ 9116 ✓	FRONT PASSENGER AIRBAG	1.00	24040520	A/I/W
MA447 860 37 85/ 9C94 ✓	SEAT BELT	1.00	24040520	A/I/W
MA447 860 25 85/649C94 ✓	SEAT BELT	1.00	24040540	A/I/W

Part Requisition Approved By :




Received By :

Name :

Date/Time :

Signature :

  
24/3/2024