

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 26 February 2021 6:00 PM
To: Edwin Abcede Caina
Cc: SUR; Coco Lu Ting; Kevin Leong Wai Kit; Don Bong Kiong Hua; Andre Chow En De
Subject: RE: AIG-OD SGB 3377A DOA: 23/02/2021

Dear Edwin,

Please take note that the excess \$0/-.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 26 February 2021 5:59 PM
To: Edwin Abcede Caina <edwin.caina@cyclecarriage.com.sg>
Cc: SUR <sur@lkkauto.com>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Kevin Leong Wai Kit <kevin.leong@cyclecarriage.com.sg>; Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>
Subject: AIG-OD SGB 3377A DOA: 23/02/2021

Dear Edwin,

As instructed by our client, please proceed to repair the insured vehicle **SGB 3377A (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Note: Kindly arrange our surveyor to conduct resurvey of odometer reading & before paint for all panels and parts.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)