



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|---|-----------------------------|------------|
| SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 | | | Ref: CS4/SMO21002651/Kqf3e2 | |
| | | | Date: 27/04/2021 | |
| | | | Code: SMO | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GBE 5165A | Veh. Inspected | BICYCLE |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | CMTD2100626/GPL | Excess (\$) | 0.00 |
| | Assign From | GRACE TEO | Assign Date | 26/02/2021 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | COLNAGO C60 | c.c | 0 |
| | Engine No. | HIDDEN | Year of Reg. | |
| | Chassis No. | | Colour | WHITE |
| | Odometer | - | Steering | |
| | Brakes | | Modification | |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 700C | CONTINENTAL | mm |
| | L/H Front Tyre | 700C | CONTINENTAL | mm |
| | R/H Rear Tyre | 700C | CONTINENTAL | mm |
| | L/H Rear Tyre | 700C | CONTINENTAL | mm |
| 4. Description of Damages | | | | |
| | THE BICYCLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 19/02/2021 | Inspection Date | 26/02/2021 |
| | Survey held at | 160 SIN MING DRIVE #06-20 SIN MING AUTOCARE | | |
| | Repairer | R C AUTO | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |