



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

IMMEDIATE ADVICE

To : AXA Insurance Pte Ltd

DATE: 1/3/21

Survey details

| | |
|---------------------|---------------------|
| Date of loss | 13/2/2021 |
| Date of appointment | 26/2/2021 |
| Date of survey | 26/2/2021 |
| Location of survey | EQUATOR BROTHERHOOD |

Vehicle Details:

| | |
|----------------------|---------------|
| Claim Type: | THIRD PARTY |
| Vehicle number | FX 898D |
| Make and Model | HONDA PHANTOM |
| Date of registration | 22/8/2003 |
| Excess | |
| Market Value | \$5,000.00 |
| Part Rebate | \$420.00 |
| Nett Loss | \$4,580.00 |

Repair details

| | |
|------------------|--|
| Initial Estimate | |
|------------------|--|

Proposed/Revised repair cost:

| | |
|--------------------------|--------------|
| Parts | |
| "Check items (Estimated) | |
| Labour | |
| Total | |
| Lump Sum (Estimated) | |
| | |
| Number of days of repair | 3 days (est) |

Remarks:

The estimated repair cost of the damaged vehicle is in the region of \$2,000.00-\$3,000.00