

Vehicle Number : SGV8343J

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------	------------------------------

List Items

1 pc	Front bumper	bent	\$ 2,250.00	\$ 1015.00 2,250.00 CUT ✓
1 pc	Front bumper side retainer	bent	\$ 88.00	\$ 25.00 88.00 NEW ✓
1 pc	Front bumper side bracket	bent	\$ 64.50	\$ 64.50 NDX

	Parts Sub-Total	\$	2,402.50	\$	2,402.50
Discount	10.00%	\$	240.25	\$	240.25
		\$	2,162.25	\$	2,162.25

Vehicle Number : SGV8343J

SPARE PARTS

@ 10%
 1040.00
 104.00
 936.00

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------	------------------------------

Special Nett Items

1 pc	Front bumper sensor	electronically shocked	\$ 250.00	\$ 215.00 250.00 SC ✓
------	---------------------	------------------------	-----------	----------------------------------

Special Nett Sub-Total	\$	250.00	\$	250.00
------------------------	----	--------	----	-------------------

Spare Parts Total	\$	2,412.25	\$	2,412.25
-------------------	----	----------	----	---------------------

215.00

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
	Spare Parts Total c/f	\$ 2,412.25	\$ 2,412.25
1	To tuff coat affected areas	\$ 180.00	\$ 150.00 <i>NNX</i>
2	To respray affected areas	\$ 1,400.00	\$ 1,200.00 <i>100.00</i> ✓
3	To renew damaged parts, straighten and repair front chassis member and aligned all parts	\$ 1,400.00	\$ 1,200.00 <i>600.00</i>
4	To polish and coating for new paint <i>* Coating invoice required</i>	\$ 1,200.00	\$ 1,200.00 <i>400.00</i>
5	To remove and replace front sensor	\$ 150.00	\$ 120.00 <i>60.00</i>
	Total	\$ 6,742.25	\$ 6,282.25

The repairer has agreed to undertake the repair under a part by part Sum Basis. We have further adjusted the amount to a part by part Sum Repair of :

\$ 5,500.00

Fong
Fong Kok Heng
Qualified Appraiser



PARTS 936.80
 SN 215.00
 LABOUR 1460.00
 @ 200% 522.20
 2088.80

L/S 2100/2

Repair days 4