

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd

AIG Building

78 Shenton Way #08-16

Singapore (079120)

ATTN: MOTOR CLAIM DEPARTMENT

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: GBH3083A

MODEL : Nissan NV350

POLICY NO : M0015539

CHASSIS NO : JN1MC2E26Z008711

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 17/2/2021

Page : 1 of 2

DATE / TIME OF ACCIDENT: 17/02/2021 Time: 08:20Hrs at Duke Road

THIRD PARTY VEHICLE NO: SJK6817U

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

## Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1	FRONT BUMPER <i>Cut</i>	572.00		572.00 ✓
2	BUMPER CLIPS <i>44</i>	5.50	10	55.00 X
3	FRONT RIGHT FENDER <i>Door Dent</i>	535.00		535.00 ✓
4	FRONT RIGHT DOOR REGISTRATION STICKER <i>44</i>	35.00		35.00 ✓
5	FRONT HEAD LAMP RH <i>Scratched</i>	481.00		481.00 ✓
5	FRONT RH FOG LAMP <i>44</i>	321.00		321.00 X
6	FRONT RH FOG LAMP BRACKET <i>44</i>	118.00		118.00 X
7	FRONT GRILLE <i>44</i>	479.00		479.00 X

1623.00  
1073 1460.70

Sub-Total: 2,596.00

Total Parts : 2,596.00

## Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts. (Front)	700.00 <i>450/-</i>
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	860.00 <i>700.00 400/-</i>
3	Provide skill labour to dismantle and transfer door and window	200.00 <i>60/-</i>
4	Provide skill labour to wheel alignment	150.00 <i>44</i>
5	Provide skill labour to check undercarriage	150.00 <i>44</i>

Total Labour:

26/02/2021 @ 1700hr  
Hot Antenna  
2/5mm & 3 days.  
Ryan  
2kk Antenna  
2320.70  
1/5 1800/-  
Total Parts & Labour:  
GST 7%  
Grand Total:

1,900.00  
4,496.00  
314.72  
4,810.72