

LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YP962T190530

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 26-02-21

Address: Motor Claims Department

Vehicle No: YP962T

78 Shenton Way #07-16

Model/Make: Mitsubishi

AIG Building

Singapore 079120

Canter FEB21ER3SDEB (CBU)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Wheel Fender <i>be/cno</i> <i>652</i>	\$ 480.00	<input checked="" type="checkbox"/>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 150.00	<i>-100</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 630.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

not Authored
slar
d/s \$ 350
2 days
the phan...

slar Cecilia

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: