

JERGA DETAILS

UEN: 201736810K
61 Woodlands Industrial Park E9, E9 Premium, #01-02 Singapore 757047

Invoice

Date : 22/01/20
 Invoice Number : 22/01/20/06
 Car Brand & Model, Colour, License Plate : Mercs 4200 - Grey - SKC 959 M

Description	Amount
1. Paint Protection Coating <input type="checkbox"/> a. CAMUI CC4 <input type="checkbox"/> b. CAMUI Golden Expresser <input checked="" type="checkbox"/> c. ULTIMEA Self Heal Coating	\$ 400
2. Platinum99 Solar Film <input type="checkbox"/> Full Car <input type="checkbox"/> Half Car <input type="checkbox"/> Others Remarks: _____	
3. Transition Solar Film <input type="checkbox"/> Full Car <input type="checkbox"/> Half Car <input type="checkbox"/> Others Remarks: _____	
4. Paint Protection Film (ULTIMEA FusionUltra Pro) <input type="checkbox"/> a. Full Car <input type="checkbox"/> b. Full Front <input type="checkbox"/> c. 4 Doors <input type="checkbox"/> d. Others Remarks: _____	
5. Others <input type="checkbox"/> a. Remarks: _____	

Total Amount Payable:

\$ 400/=

JERGA PTE, LTD.
 UEN REG NO.
 201736810K

Company Stamp



m: 98448533
t: 63855510
w: www.detaillab.com.sg

PREMIER@Kaki Bukit, 8 Kaki Bukit Ave 4, #02-03/04 S415875

XIN YUN AUTO PTE LTD
SKC959M

INVOICE: 202103211
DATE: 16/3/21
VEHICLE NO.: SKC959M
MAKE/MODEL: MERC
CHASSIS/ENGINE NO.:

DESCRIPTION	QTY	AMOUNT S\$
COATING SYSTEM	1	\$250.00

E. & O. TOTAL S\$: \$250.00

*Please make cheque payable to "DETAIL LAB"



DETAIL LAB



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SKC959M Mercedes AMG Hybrid A200

No	Qty	Parts Description	Estimated Parts Price
1	1	Bumper assy	\$ 2,250.00 de ✓ 1550.1
2	2	Bumper side retainer	\$ 190.00 de ✓
3	2	Bumper side spacer	\$ 205.00 de ✓
4	1	Bumper sensor left	\$ 250.00 nm ✓ 190
5	1	Bumper sensor center	\$ 250.00 nm ✓ 190
6	2	Sensor casing	\$ 100.00 net ✓
7	1	Switch module carrier basic carrier	\$ 325.00 x
8	2	Sensor rear switching module	\$ 750.00 x } nh
9	2	Rear bumper sensor electric cable	\$ 400.00 x
10	2	Switch sensor	\$ 500.00 x
11	1	Emblem	\$ 165.85 na ✓
12	1	A200 Logo	\$ 158.36 na ✓
13	1	Tailgate assy	\$ 2,500.00 R ✓
14	1	Tailgate lock	\$ 185.00 x nm
15	2	Tailgate hinges	\$ 197.20 R ✓
16	2	Tailgate hinges bracket	\$ 220.00 R ✓
17	1	Taillight left	\$ 775.75 na x nm
18	1	Reinforcement	\$ 850.00 bt ✓ 585
19	1	Reinforcement top cover garnish	\$ 325.00 c na ✓
20	1	Rear bumper lower lip	\$ 180.00 na x
21	1/2	Silving lining / lower chrome	\$ 375.00 at ✓
22	1/2	Lower trim /black	\$ 616.00 de ✓ 450
23	2	Exhaust support silver chrome	553.00 \$ -353.10 LH-at ✓ 276.50 RH x nm
24	1	Lower bumper undercarriage bottom	\$ 225.00 na ✓
Parts sub-total			\$ 12,346.26



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SKC959M Mercedes AMG Hybrid A200

No	Qty	Parts Description / Special Nett Item	Estimated Parts Price
1	12	Bumper clips	\$ 80.00 30 net ✓
2	10	Lower cover clips	\$ 40.00 20 net ✓
3	10	Insulator clips	\$ 30.00 x
4	6	Tailgate seal clips	\$ 50.00 x } nm
5	8	Support panel garnish clips	\$ 30.00 x
6	1	Number plate with cashing	\$ 80.00 x
7	1	Programming / Coding	\$ 500.00 200
Special Nett Items			\$ 810.00 250.

4.
4985.71
10% 4487.14



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SKC959M Mercedes AMG Hybrid A200

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area	\$ 1,500.00
2	To putty and spray painting behind portion.	\$ 1,800.00
3	To dismantle both taillight, repalce the taillight check wiring and focus behind headlamp.	\$ 150.00
4	To apply anti rust proofing to front affected area.	\$ 200.00
5	To remove and install front undercarriage parts.	\$ 150.00 x
6	To balance the wheel.	\$ 80.00 x
7	To conduct wheel alignment.	\$ 120.00 x
8	To remove and install tailgate lock mechanism assy.	\$ 100.00
9	To remove and install rear bumper sensor.	\$ 120.00
10	To conduct chassis alignment.	\$ 150.00 x
11	To dismantle the tailgate internal trims to assist the repair	\$ 120.00

Total labour : \$ 4,490.00

Total parts 13,156.26

Total labour : 4,490.00

Total repair cost : 21,627.11

27,467.01

Taufik 97495749
 8/3/21 @ Han
 2/s Resurvey after repair.
 4 5 days.
 Taufik@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SKC959M Mercedes AMG Hybrid A200

No	Qty	Parts Description Supplementary	Estimated Parts Price
1	1	Rear light	\$ 2,200.00 X nn
2	2	Rear light	\$ 2,200.00 X nn.
3	2	Rear light side bracket	\$ 210.00 <i>crs</i>
4	2	Rear light support	\$ 250.00 <i>crs</i>
5	1	Tailgate top garnish <i>end panel garnish</i>	\$ 325.00 <i>dl - 185</i>
6	<i>1/2</i>	Reniforment top cover <i>- repeated item same as no. 19</i>	\$ 205.00 <i>nn.</i>
7	-	<i>ceramic coating SN \$ 250</i>	
Parts sub-total			\$ 5,390.00

paper 9/3/21

*645
10% - 580.5
SN - 250*

*4
1600
830.50
6897.64
45895500
5 days*

*4487.14
250
1700
830.50
7267.64
45895800
5 days*