

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM21002742/Qga3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	18/05/2022	
	ATTN:LYNN			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMX 6833T	Veh. Inspected	l	FZ 4332H	
	Policy No.	P2423942	Coverage (\$)		0.00	
	Claim No.	S1M032H7	Excess (\$)		0.00	
	Assign From		Assign Date		01/03/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA WAVE	c.c		125	
	Engine No.	HIDDEN	Year of Reg.		2005	
	Chassis No.	NF125MP0051602	Colour		RED	
	Odometer	211981 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	70/90-17	DIABLO		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	70/90-17	DIABLO		5 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	06/02/2021	Inspection Dat	е	01/03/2021	
	Survey held at	Project 8 Motorworks				
		6 Defu lane 10 #01-554 S(539187)				
5a.	ia. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				