

QUOTATION FOR REPAIR : FZ4332H

<u>Qty</u>	<u>Description</u>
1	FORK SET / BT
1	COVER SET / CRU.
1	REAR RACK / CRU.
1	BOX X N.S.
1	RHS FRONT FOOT REST RUBBER / cut
1	FRONT FOOTRET BRACKET / BT.
1	RHS PILLION FOOTREST / BT
1	RHS PILLION FOOTREST RUBBER / Mis
1	HANDLE BAR / BT
1	FORK UNDER BRACKET / BT
1	STEERING CONE BEARING / Nec.
1	FRONT RIM BEARING / Jam

Repairer's

<u>Estimate</u>
480.00 450
520.00 450
120.00 70
180.00 X
80.00 /
110.00 /
80.00 /
60.00 /
140.00 /
160.00 /
150.00 125
100.00 40

1,765
- 10%
1,588.50

	2,180.00
Less 10%	218.00
Total Part :	1,962.00

Nett items

TOWING FEE 80.00

80

Total Nett items :	80.00
Total parts :	2,042.00

Labour Fee

BODY FRAME RE-ALIGNMENT 800.00 100
 FORK RE-ALIGNMENT 380.00 X
 FRONT RIM RE-ALIGNMENT 380.00 X
 LABOUR TO DISMANTLE AND ASSEMBLE PARTS 800.00 210

Total Labour Fee:	2,360.00
Total parts and labour charges :	4,402.00

5 DAYS

310

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1,588.50
 80
 310
 1,978.50
 - 20%
 1,582.50

215

\$1,600

3 days