

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 580C

Vehicle Details

Vehicle No.: SJN1515H
Vehicle to be Exported: No
Intended Deregistration Date: 02 Mar 2021
Vehicle Make: TOYOTA
Vehicle Model: LEXUS NX300 5DR SUV (AT)(4WD)
EXECUTIVE

Primary Colour: Silver
Manufacturing Year: 2019
Engine No.: 8AR4217426
Chassis No.: JTJBARBZ902228523
Maximum Power Output: 175.0 kW (234 bhp)
Open Market Value: \$41,083.00
Original Registration Date: 24 Dec 2019
First Registration Date: 24 Dec 2019
Transfer Count: 0
Actual ARF Paid: \$49,517.00 *WYS*

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 23 Dec 2029
PARF Rebate Amount: \$37,137.00

Intended COE Rebate Details

COE Expiry Date: 23 Dec 2029
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$39,700.00
COE Rebate Amount: \$34,961.00
Total Rebate Amount: \$72,098.00

The information contained herein is correct as at 02 Mar 2021

OK

Repairer Estimates

Page 1 of 3



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD
CO. REG. No: 1995-01140-D

INSURER: ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC20A0005490	Date of Loss:	01/03/2021
Vehicle Reg. No.:	SJN1515H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SHARON ONG HWEE CHENG		
Driver:	SHARON ONG HWEE CHENG		
Make/Model:	LEXUS NX300, 2.0 E 5DR SUV (4WD) EXECUTIVE (A)	Vehicle Reg. Date:	23/12/2019
Vehicle Colour:	SILVER	Chassis No:	JTJBARBZ902228523
Engine No:	8AR4217426		
Odometer:	23000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Remarks:	VEHICLE IN WORKSHOP		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)		

Not Attached
See
Take photo before repair.
5 days
51125 \$ 500?

P/P \$

COST OF CLAIMS

	Amount
Parts	6,188.50
Miscellaneous Items	0.00
Labour	2,840.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,028.50
+ GST 7.00% (S\$)	632.00
Nett Amount (S\$)	9,660.50

This claim is handled by: JOEL NG

Generated using Merlimen e-Claims Internet Estimation & Adjusting System

Repairer Estimates

Page 2 of 3

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Mar 2021)
 Parts: M1-SUV LEXUS NX300 2.0 E 5DR SUV (4WD) EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Falcon-Air Auto Services Pte Ltd/SJN1515H/01/03/2021 14:35
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*N/S FRONT DOOR LOWER GARNISH <i>green</i>	0.00	0.00	*180.00F
2	1		*N/S REAR DOOR <i>red</i>	0.00	0.00	*900.00F
3	1		*N/S REAR DOOR LOWER GARNISH <i>D/S</i>	0.00	0.00	*180.00F
4	1		*N/S REAR DOOR ARCH GARNISH <i>D/S</i>	0.00	0.00	*125.00F
5	1		*N/S REAR DOOR WEATHERSTRIP <i>11</i>	0.00	0.00	*150.00F
6	1		*N/S REAR DOOR RUBBER <i>SLC</i>	0.00	0.00	*90.00F
7	1		*REAR BUMPER <i>CU</i>	0.00	0.00	*550.00F
8	1		*REAR BUMPER LOWER <i>11</i>	0.00	0.00	*300.00F
9	1		*REAR BUMPER CLIPS <i>11</i>	0	0.00	*50.00FS
10	1		*N/S REAR RIM <i>CU Local/Regn Hoosier</i>	0.00	0.00	*2,700.00F
11	1		*N/S REAR FENDER ARCH GARNISH <i>SLC</i>	0.00	0.00	*90.00F
12	1		*N/S REAR BUMPER ARCH GARNISH <i>green</i>	0.00	0.00	*135.00F
13	1		*N/S REAR BUMPER SIDE RETAINER <i>11</i>	0.00	0.00	*50.00F
14	1		*N/S REAR FENDER INNER SHIELD <i>11</i>	0.00	0.00	*85.00F
15	1		*N/S REAR FENDER INNER SHIELD CLIPS <i>11</i>	0	0.00	*50.00FS

F=Franchise part. S=SpaNet.

Sub Total (\$\$) 5,635.00
 + Margin on L,N Items 10.00% (\$\$) 553.50

Total Parts (\$\$) 6,188.50

Falcon-Air Auto Services Pte Ltd/SJN1515H/01/03/2021 14:35. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Repairer Estimates

Page 3 of 3

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	50.00 20
2	TRANSFER DOOR PARTS	New	120.00 60
3	COMPUTERISED WHEEL ALIGNMENT	New	120.00 60
4	TRANSFER TYRE TO NEW RIM AND BALANCING	New	50.00 X
5	TO DIAGNOSE AND RESET DOOR MEMORY	New	250.00 80
6	INSTALL REVERSE SENSOR IN NEW BUMPER	New	80.00 40
7	TO RE-INITIALISE DOOR MEMORY AND REVERSE SENSOR	New	250.00 X
8	LABOUR/PANEL BEATING	New	800.00 600
9	SPRAY PAINTING	New	1,000.00 750
10	TO REMOVE/REFIT TRIMS AND GARNISHES	New	120.00 80
Gross Labour Cost (\$\$)			2,840.00

Falcon-Air Auto Services Pte Ltd/SJN1515H/01/03/2021 14:35. Not valid without Reference section.
Generated using Merimon e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

Head Office : 8-176 Sin Ming Drive #01-08/17/13, #05-17 Sin Ming Autocentre S(575721) Tel: 6462-0890 / 6458-0889 Fax: 6454-7862
Branches : Tampines St 93 #01-200 S(528843) Tel: 6763-7997 Fax: 6788-7997 No 8 Pandan Loop S(128226) Tel: 6779-5855 Fax: 6779-1110
Website: www.falconair.com.sg Email: enq@falconair.com.sg