

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Mar 2021)
 Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SHA4679R/01/03/2021 15:19
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	*458.60 FL <i>de</i>
2	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	*318.80 FL <i>hg</i>
3	1		*REAR BUMPER CENTER GUARD	25.00	0.00	*552.60 FL <i>de</i>
4	10		*REAR BUMPER CLIPS	25.00	0.00	*22.00 FL <i>na</i>
5	1		*REAR BUMPER SIDE RETAINER LH	25.00	0.00	*112.70 FL <i>run</i>
6	1		*REAR BUMPER EXTENSION LH	25.00	0.00	*232.00 FL <i>ru</i>
7	1		*TAILLAMP UPPER LH	25.00	0.00	*557.90 FL <i>run</i>
8	1		*TAILLAMP LOWER LH	25.00	0.00	*548.40 FL <i>cut</i>
9	1		*TAILGATE OUTER GARNISH	25.00	0.00	*889.70 FL <i>ru</i>
10	1		*TAILGATE EMBLEM-PRIUS	25.00	0.00	*60.80 FL <i>na</i>
11	1		*TAILGATE EMBLEM-HYBRID	25.00	0.00	*52.40 FL <i>na</i>
12	1		*TAILGATE EMBLEM-TOYOTA STAR	25.00	0.00	*52.90 FL <i>na</i>
13	1		*TAILGATE COMFORTDELGRO	0.00	0.00	*30.00 F <i>na</i>
14	1		*TAILGATE 65521111	0.00	0.00	*30.00 F <i>na</i>
15	1		*TAILGATE APPS STICKER	0.00	0.00	*40.00 F <i>na</i>
16	1		*REVERSE SENSOR	0.00	0.00	*135.70 F <i>na</i>
17	1		*REAR BUMPER MAT	0.00	0.00	*50.00 F <i>na</i>
18	1		*REAR NO.PLATE WITH TRIM COVER	0.00	0.00	*55.00 F <i>na</i>

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,199.50
- List Item Discount on L Items (S\$)	964.70
Total Parts (S\$)	3,234.80

ComfortDelGro Engineering Pte Ltd/SHA4679R/01/03/2021 15:19. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

3188.20
 25% = 2391.15
 sum 340.70

4794.80

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	525 800.00
2	SPRAY PAINTING	New	500 600.00
3	CHECK LIGHTINGS/ WIRINGS	New	30 40.00
4	R/I REVERSE SENSOR	New	30 120.00
Gross Labour Cost (S\$)			1,560.00

ComfortDelGro Engineering Pte Ltd/SHA4679R/01/03/2021 15:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5) TOWING FEE \$ 60.00 net ✓ 1145

W/Abn 3896.85
 Tanpin 97495749 4593100
 WP 213/210440
 1/3 Resurvey after repair # 3 days
 Tanpin @ 1/11 auto-w 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Patch prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Accepted by Repairer

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TOWING FEE	New <i>nil</i> ✓	60.00
Gross Labour Cost (S\$)			<u>60.00</u>

ComfortDelGro Engineering Pte Ltd/SHA4679R/04/03/2021 09:41. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >