



Service Request Details

Claim
S1M0344A

Reference
None 

Loss Date
February 20, 2021

Report Date
Mar 1, 2021 2:01:28 PM

Request Date
March 2, 2021

Due Date
March 2, 2022

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pre-Repair Survey

Actions

Next Step
Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #
SMF9464A

Model
C 180

Service Address

, , ,

Primary Contact/Insured

BIS MOTORING PTE. LTD.
20 BENDEMEER ROAD, #03-13/14 BS BENDEMEER CENTRE, 339914, Singapore
66815720
gismotoring13@gmail.com

Claim Handler

Chu Xichi Eugene

eugene.chuxc@axa.com.sg
Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

New Message

TYPE	
SENT	3/2/21 3:38 PM
FROM	LKK AUTO CONSULTANTS PTE LTD (TP)
SUBJECT	Vehicle not in
BODY	Please be informed that vehicle is not in the work...
	