

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	tef:	CS/AGI21002830/Aqd3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	28/04/2021	
			С	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJB 9072D	Veh. Inspected		SY 7475K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10009204	Excess (\$)		0.00	
	Assign From	STANLEY LAI	Assign Date		02/03/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ ML350	c.c		3498	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	WDC1641862A469442	Colour		BLACK	
	Odometer	123044 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.						
		Size	Make		Balance	
	R/H Front Tyre	255/50 R19	CONTINENTAL		6 mm	
	L/H Front Tyre	255/50 R19	CONTINENTAL		6 mm	
	R/H Rear Tyre	255/50 R19	CONTINENTAL		6 mm	
	L/H Rear Tyre	255/50 R19	CONTINENTAL		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	25/02/2021	Inspection Date		02/03/2021	
	Survey held at	KT MOTORWERK				
		3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: