

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 04 Mar 2021

Preliminary Advice

Vehicle No	: SJY3005S	Accident Date	: 02/03/2021
Make	: CITROEN C4	Policy No.	: 2100460768
Assignment Date	: 02/03/2021	Excess	: S\$600.00
Date of Inspection	: 03/03/2021	Est. Duration of Repair	: 7
Inspection At	: CYCLE & CARRIAGE FRANCE PTE LTD (PANDAN GARDENS) (HQ) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,386.60
Revised Amount	:S\$	6,811.40
Check Items (Estimated)	:S\$	272.00
Total	:S\$	7,083.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	41,670.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,330.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :