



HUA HONG PRIVATE LIMITED

250 SUNGAIKADU STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

07 May 2019

QUOT201905-000014
HHTPCLAIMS19-70

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET, #04-00 / #05-00
IOB BUILDING
SINGAPORE 049711

Attn: Motor Claims Department

**ACCIDENT INVOLVING GY9392U & SHA4974M ON 09/03/2019 JUNCTION OF BT BATOK ST
23 & BT BATOK EAST AVE 3 AT ABOUT 2235 HOURS**

Insured : EVERGREEN GENERAL CONTRACTORS
Vehicle Registration No. : GY9392U
Vehicle Make : HYUNDAI
Vehicle Model : HRL0WDECK2.5
Vehicle Chassis No. : KMFZCN7HR5U077805
Policy No. : DMCG18003595
Date of Accident : 09/03/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$	Notes
1	1	Front Bumper		\$ 512.10	/CRK
2	2	Front Bumper Retainer (LH/RH)	\$ 38.00	\$ 76.00	? /CRK
3	10	Front Bumper Clip	\$ 3.00	\$ 30.00	/NEU
4	1	Front Grille		\$ 43.50	/DEF
5	1	Emblem		\$ 40.80	/NEU
6	1	Front Panel		\$ 1,341.10	XR
7	1	Front Head Lamp (LH)		\$ 373.80	/SVC
8	1	Front Corner Panel (LH)		\$ 109.10	XR
9	1	Front Oil Cooler		\$ 495.00	/DEF
10	1	Front Reinforcement		\$ 303.10	? X SVC
11	1	Front Reinforcement Bracket (LH/RH)	\$ 65.00	\$ 65 130.00	? X DEF (LH) (RH) SVC
			Less 10%	\$ 345.45	
				\$ 3,109.05	
12	1	Front Number Plate	NETT	\$ 35.00	/CRK
To dismantle, cut & weld front panel, front bumper, front grille, front LH head lamp, front reinforcement, knocking & pull straight front chassis frame and all area affected by accident.				\$ 800.00	450
To perform wire checking.				\$ 20.00	/NEU
To spray front panel, front grille, front bumper and front reinforcement.				\$ 800.00	500
				\$ 4,764.05	
			7% GST	\$ 333.48	
				Total \$ 5,097.53	

Consultants hence notify
repairer of the following:
• Survey before/after spray painting
• Display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



[Handwritten signature]

22/5/19 1130
LIS
3 days
- CHECK ITEMS (PHOTOS)
- AFTER REPAIR PHOTOS

CONTINUE NEXT PAGE
- COE EXP 28/9/20. Less 1yr. Need to check MV.
Co Reg No 200900309M | huahong.com.sg | GST Reg No 200900309M



HUA HONG PRIVATE LIMITED

25D SUNGEL KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Supplementary List

03 March 2020

QUOT201905-000014

HHTPCLAIMS19-70

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET, #04-00 / #05-00
IOB BUILDING
SINGAPORE 049711

Attn: Motor Claims Department

**ACCIDENT INVOLVING GY9392U & SHA4974M ON 09/03/2019 JUNCTION OF BT BATOK ST
23 & BT BATOK EAST AVE 3 AT ABOUT 2235 HOURS**

Insured : EVERGREEN GENERAL CONTRACTORS
Vehicle Registration No. : GY9392U
Vehicle Make : HYUNDAI
Vehicle Model : HRL0WDECK2.5
Vehicle Chassis No. : KMFZCN7HR5U077805
Policy No. : DMCG18003595
Date of Accident : 09/03/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Washer Tank Motor		\$ 55.00
				\$ 55.00
			Less 10%	\$ 5.50
				\$ 49.50
				\$ 49.50
			7% GST	\$ 3.47
			Total	\$ 52.97

BRK

PARTS \$1,691.20
 LESS 10% \$1,522.08
 SINNETT \$ 35.00
 LABOUR \$ 970.00
\$2,527.08
 LESS LS 20% \$2,021.66
\$2,000.00 / 3 REPAIR DAYS

Authorised by Claims Dept