

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.03.2021

Time: 13:22:03

Page: 1

China Taipei (LKS)
LKK-

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305456320
 REGN NO : SHD3054J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 14.07.2016
 DATE/TIME IN : 01.03.2021 09:25
 ACCIDENT DATE : 28.02.2021

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	1	1,106.00	20.00	884.80	/ BR
0002	04-01-0103-0783-G	REAR BUMPER SIDE BRKT RH	1	35.60	20.00	28.48	X NN
0003	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	/ MC
0004	04-01-0103-0585-A	TAILLAMP RH	1	697.80	20.00	558.24	/ CPA
0005	04-01-0103-0658-G	REAR WHEEL CAP RH	1	217.20	20.00	173.76	/ CA
0006	04-01-0103-0575-G	REAR FENDER RH	1	2,171.40	20.00	1,737.12	X Base Repair
0007	03-01-0103-0122-G	REAR FENDER SHIELD RH	1	169.30	20.00	135.44	/ CA
0008	04-01-0103-0595-G	REAR DOOR RH	1	2,201.10	20.00	1,760.88	X Repair
0009	04-01-0103-0745-G	REAR WINDSCREEN MOULDING	1	51.80	20.00	41.44	X MC NN
0010	04-01-0103-1150-A	REAR BUMPER MAT	1	50.00		50.00	/ MC
0011	28-01-9999-2023-A	REAR DOOR APPS STICKER RH	1	80.00		80.00	/ MC
0012	05-01-0199-0032-A	WINDSCREEN AHESIVE-310ML	2	92.00		92.00	X MC NN

SUB-TOTAL : 5,559.76

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.03.2021

Time: 13:22:03

Page: 2

China Taiping (L/S)

L&P

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305456320
 REGN NO : SHD3054J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 14.07.2016
 DATE/TIME IN : 01.03.2021 09:25
 ACCIDENT DATE : 28.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0000 PB	PANEL BEATING	900.00	560	
0001 SP	SPRAYPAINT CHARGE	900.00	750	
0002 17-01	CHECK ALL LIGHTING	40.00	30	
0003 20-00	TUFF COAT ON AFFECTED PARTS.	60.00	X NN	
0004 L	R/I REVERSE SENSOR	120.00	40	
0005 L	R/I UPHOPSTERY ETC	150.00	60	
0006 L	R/I REAR WINDSCREEN	150.00	X NN	
0007 L	WHEEL ALIGNMENT	120.00	60	
		SUB-TOTAL : 2,440.00		

4 Days

L/S

After repair photos.

Gene Qs up

01/3/21

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.03.2021

Time: 13:22:03

REPAIR ESTIMATE

China Taiping 445)

Page: 3

B TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305456320
REGN NO : SHD3054J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 14.07.2016
DATE/TIME IN : 01.03.2021 09:25
ACCIDENT DATE : 28.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 7,999.76

Lmfs

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE
DATE :